

SLV4693R. 2017 Dec
Toyota Sienna Hybrid.
XHP1707105869.

TP AXA
Denise,

Rear Bumper	Distorted	758.40	✓
Rear Bumper Clips.	new	30(SN).	✓
Rear Bumper Side Holder x 02	And	$75.4 \times 2 = 150.80$	✓
Rear Bumper Centre Protector	Dehd	207.40.	✓
Rear Bumper Side Protector x 02	Dehd	$151.1 \times 2 = 302.20$	✓
Rear Bumper Reflector x 02	Crushed	$85.4 \times 2 = 170.80$	✓
Reverse Sensor	Damaged	280(SN) 200(SN)	
Rear End Panel Outer	Distorted	599.40	✓
Rear End Panel Inner.		607.80	✓
Rear End Panel Top Garnish	Dehd	208.40.	✓
Rear End Panel Top Garnish Clips.	new	20(SN)	✓
Rear End Panel Sealant.	new	60(SN)	✓
Rear End Panel Antenna Sensor	Crushed	127.90	✓
Tail Lamp x 02	Cut	$407 \times 2 = 814$	✓
Tail Lamp Panel x 02	Distorted	$385.9 \times 2 = 771.80$	✓

SLV 4693R.

Tailgate	Distorted	1186.90	/
Tailgate Lock	Reas'd	265.80	/
Tailgate Weatherstripe.	Wt	385.40	/
Tailgate Outer Garish.	Del'd	209.90	/
Tailgate Outer Operer Switch.	HP New	128.90	X
Tailgate Reflector x 02	HP Wt Ref and	$281.4 \times 2 = 562.80$	✓
Tailgate Damper x 02	HP Wt	$291.5 \times 2 = 583$	X
Tailgate Inner Trim	Torn	251.80	/
Tailgate Inner Trim clips.	New	30(SN)	/
Tailgate Glass	Shattered	1181.90.	/
Tailgate Glass Moulding	? New	123.40.	/
Tailgate Glass Sealant		60(SN)	/
Tailgate Glass Solar Film	New	280(SN) 200(SN)	/
Tailgate Wiper Arm	Wt	101.40.	/
Tailgate Wiper Arm Cover.	Wt	24.90	/

SLV 4693R.

Tailgate Wiper Blade Cut 61.40 ✓

Tailgate Wiper Motor Damaged 646.70 ✓

Toyota Logo 55.80 ✓

Hybrid Emblem. 68.90 ✓

Toyota Stickers. 29.40 ✓

Rear Fender Outer Cover x02 cracked 415.6 x 2 = 831.20 ✓

Rear Fender Inner Trim Board x02 Deformed 713.2 x 2 = 1426.40 ✓

Rear Fender Inner Trim Board Clips. 60(SN) ✓

Rear Fender Inner Shield x02 LIT torn 128 x 2 = 256 128

Rear Fender Inner Shield Clips. 40(SN) 20(SN)

Floor Panel. Repair 768.60 X

Floor Panel Top Board LH Deformed 285.40 ✓

Floor Panel Top Board RH. 313.50. X

Floor Panel Inner Trim Board. 433.90. X

SLV 4693R.

Tools Utility Tray. Deband

394.10 ✓

Rear Exhaust Pipe.

885.90 X

Rear Exhaust Pipe Manifold

35.40 X

Rear Exhaust Pipe Gasket.

32.90 X.

Rear Number Plate Deband

30(SN) ✓

Rear Number Plate Holder Deband

30(SN) ✓

Rear Number Plate Lamp x02. NP

63.1 x 2 = 126.20 X

Third Brake Light At

294.90 ✓

Rear Camera. NP

480(SN) X

Rear Video Recorder Deband

~~500(SN)~~ 380(SN)

Front Number Plate NP

30(SN) X

Front Number Plate Holder NP

30(SN) X

Front Bumper Rep's

592.40 X

Front Bumper Clips NP

30(SN) X

Front Bumper Side Holder x02

70.4 x 2 = 140.80 X

SLV 4693R.

Front Bumper Logo. ¹⁴ 78.20 ✓

Front Bumper Grille ¹⁴ 846.40 ✓

Front Bumper Chrome Grille ¹⁴ 188.90. X

Front Bumper Reinforcement ¹⁴ 394.10. X

14091.50

10568.62

S.N: 1120

Panel Beating

Spray Painting

Wiring.

To remove sensor

To remove rear camera.

To remove rear video recorder.

To remove upholstery.

To remove exhaust pipe.

To spray buff. coat

~~1800~~ 1300.

~~1800~~ 1200

~~100~~ 30

~~100~~ 50

~~100~~ 50

~~100~~ 50

~~150~~ 60

150 X

~~150~~ 60.

SLV 4693R.

To replace tailgate g/s

3060

~~180~~ 120

To transfer tailgate fittings.

~~150~~ 80

To vacuum and clean up g/s shards.

~~150~~ 60.

total: 14748.62

2/5 11.8k

08 Days.

25742.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11.8k.