



AXA Insurance Pte Ltd
8 Shenton Way #24-01 AXA Tower
Singapore 068811

VEHICLE DAMAGE INSPECTION REPORT

CLAIM REFERENCE

Our Ref. No.	: 24602	Claim Number	: S0M02N2H
Accident Date	: 18-03-2020	Insured Vehicle	: YM4184L
Survey Date	: 28-04-2020	Claim Type	: Third Party
Report Date	: 21-05-2020		

DESCRIPTION AND IDENTIFICATION OF VEHICLE

Vehicle No.	: SFL928P	Chassis No.	: WPOZZZ99Z1S682551
Registration Date	: 31-03-2001	Engine No.	: 64104608
Make	: PORSCHE	Engine Cap.	: 3600 cc
Model	: 996 TURBO	Transmission	: Automatic
		Colour	: Silver

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Foot Brake	: Serviceable	Steering	: Serviceable
Hand Brake	: Serviceable	Modification	: None
Odometer	: 150884 Km		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE</u>
FRONT RH	235/40 R19	MICHELIN	4 mm
FRONT LH	235/40 R19	MICHELIN	4 mm
REAR RH	305/30 R19	MICHELIN	4 mm
REAR LH	305/30 R19	MICHELIN	4 mm

SURVEY CONDUCTED PLACE

SPEED CLINIC
 10 Ang Mo Kio Industrial Park 2A
 #02-07 AMK Autopoint SINGAPORE 568047

INSPECTION SUMMARY

Workshop Estimate	: S\$ 56871.00
Our Recommendation	: S\$ 8700.00 (lumpsum)
Estimated Repair Period	: 3 working days

We have not authorised repairs. This survey was carried out on without prejudice basis.

INFINITI APPRAISAL SERVICE

RECOMMENDED SPARE PARTS

#	Qty	Parts Description	Condition	Repairer's Estimate (S\$)	Our Adjustment (S\$)
LIST ITEM					
1	1	Muffler Gruppe M (eol)	Dented	13584.00	8656.76
2	2	O2 Sensors 996-606-128-01	Reuse	3018.00	0.00
3	2	O2 Sensors 996-606-138-01	Reuse	3428.00	0.00
4	16	Nuts 7 999-084-052-02	Reuse	245.00	0.00
5	8	Washer 900-031-032-02	Reuse	185.00	0.00
6	2	Gasket 996-111-217-70	Bent	209.00	209.00
7	1	Muffler Hanging Bracket 996-111-024-71	Necessary	259.00	259.00
8	1	Heat Shield 996-505-471-00	Deformed	140.00	140.00
9	4	Heat Shield Lock Nut 999-049-025-09	Necessary	13.00	13.00
10	1	Extractors	Reuse	6260.00	0.00
11	2	Header Gasket 996-111-107-71	Reuse	85.00	0.00
12	18	Header Bolts 900-378-227-09	Reuse	266.00	0.00
13	1	Turbocharger	Not Necessary	12520.00	0.00
14	14	Studs	Not Necessary	215.00	0.00
15	2	Oil Feed Check Valve	Not Necessary	529.00	0.00
16	2	Oil Restrictor Sealaing Ring	Not Necessary	4.00	0.00
17	1	Hanger Bracket, Lhs	Not Necessary	261.00	0.00
18	1	Hanger Bracket, Rhs	Not Necessary	166.00	0.00
19	4	Oil Reservoir Bolt	Not Necessary	47.00	0.00
20	2	O-ring Oil Reservoir	Not Necessary	24.00	0.00
21	1	Turbo Intake Manifold Lhs	Not Necessary	369.00	0.00
22	1	Turbo Intake Manifold Rhs	Not Necessary	369.00	0.00
23	1	Engine Oil 10 Quart	Not Necessary	300.00	0.00
24	1	Oil Filter	Not Necessary	61.00	0.00
25	1	Coolant	Not Necessary	90.00	0.00
TOTAL				42647.00	9277.76
SPECIAL NETT ITEM					
1	1	Chassis Dynamometer, 4-wheel, 13 Runs	Necessary	2000.00	800.00
TOTAL				2000.00	800.00

RECOMMENDED LABOUR

#	Job Description	Repairer's Estimate (S\$)	Our Adjustment (S\$)
1	Labour	9000.00	200.00
2	Dme speed density recalibration	3224.00	600.00
TOTAL LABOUR COST		: 12224.00	800.00

COST OF CLAIM

Description	Repairer's Estimate (S\$)	Our Adjustment (S\$)
Total Recommended Parts	: 44647.00	10077.76
Total Recommended Labour	: 12224.00	800.00
Total Cost of Claim	: 56871.00	10877.76

INFINITI APPRAISAL SERVICE**OUR FINDINGS AND RECOMMENDATION****OUR FINDINGS**

At the place of survey, we saw this vehicle sustained rear portion damage.

The damages seen during our survey were muffler gruppe m (eol),gasket,muffler hanging bracket,heat shield and etc being damaged.The detailed description of the damages is listed as 'RECOMMENDED SPARE PARTS'.

OUR RECOMMENDATION

SPEED CLINIC estimated a repair cost of S\$56871.00. We adjusted it to S\$10877.76 on a part-by-part basis.

We recommend repairs to this vehicle be carried out on a lumpsum basis at S\$8700.00 .

The repairs would require a period of 3 working days.

We submit our inspection report for your kind attention and would add the inspection was carried out to the best of our ability, knowledge and experience.



Edward Cho
INFINITI APPRAISAL SERVICE



Cedric Ng
INFINITI APPRAISAL SERVICE