

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122003458/DQY3Q2**Date:** 04/11/2022REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG21008133
Claimant Vehicle No :	SH6616S	Insured Vehicle No :	YP9045G
Date of Loss:	09/04/2022	Nature of Claim:	TP
		Claim No:	CDMCG22000644

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6616S		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU408490
Reg. Date:	19/12/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU189771
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,253.16	38,456.28	11,796.88	23.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,660.00	2,860.00	4,800.00	62.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	57,913.16	41,316.28	16,596.88	28.66
Approved Total (Overridden) (\$\$)		33,000.00		
(\$\$)	57,913.16	33,000.00	24,913.16	43.02
+ GST 7.00/7.00% (\$\$)	4,053.92	2,310.00	1,743.92	43.02
Nett Amount (\$\$)	61,967.08	35,310.00	26,657.08	43.02

INSPECTION

Date of Assignment:	14/04/2022	
Date Inspected:	18/04/2022	Inspected At:
		8 KAKI BUKIT AVENUE 4
		#01-49 PREMIER @ KAKI BUKIT
		SINGAPORE 415875
Estimated Period of Repair:	16.0 days	Repairer: Bifrost Auto Pte Ltd (sin Ming) (HQ)

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2022)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH6616S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,253.80 FL	*2,253.80 FL
2	2		*BONNET HINGE (LH/RH)	Bent	237.40 FL	*237.40 FL
3	1		*BONNET MOULDING	Not fitted	41.40 FL	*- FL
4	1		*BONNET LOCK	Bent	127.30 FL	*127.30 FL
5	1		*BONNET INSULATOR	Not Necessary	230.10 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
7	1		*RADIATOR GRILLE NEW MODEL	Broken	1,568.60 FL	*1,568.60 FL
8	2		*FLAP ASSY ACTIVE AIR UPPER (LH/RH)	Broken	1,649.20 FL	*1,649.20 FL
9	1		*SPEAKER ASSY -VESS	Broken	554.40 FL	*554.40 FL
10	1		*FLAP ASSY ACTIVE WIRE	Socket Broken	765.30 FL	*765.30 FL
11	1		*FRONT NUMBER PLATE GARNISH	Dented	188.00 FL	*188.00 FL
12	1		*FRONT BUMPER COVER	Torn	481.10 FL	*481.10 FL
13	1		*FRONT BUMPER TOP COVER	Broken	476.30 FL	*476.30 FL
14	1		*FRONT BUMPER SPONGE	Torn	186.90 FL	*186.90 FL
15	1		*FRONT BUMPER REINFORCEMENT	Dented	1,136.70 FL	*1,136.70 FL
16	2		*FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH)	Bent / Dented	373.00 FL	*373.00 FL
17	1		*FRONT BUMPER TOWING COVER	Dislodged	29.00 FL	*29.00 FL
18	1		*FRONT BUMPER MOULDING CENTRE UPPER	Cut	368.50 FL	*368.50 FL
19	1		*FRONT BUMPER MOULDING	Not fitted	93.60 FL	*- FL
20	1		*FRONT BUMPER LOWER STIFFNER	Bent	285.10 FL	*285.10 FL
21	1		*FRONT BUMPER LOWER GRILLE	Broken	365.30 FL	*365.30 FL
22	1		*FRONT BUMPER LOWER GRILLE MOULDING	Cut	127.60 FL	*127.60 FL
23	1		*FRONT BUMPER LIP	Not Necessary	35.10 FL	*- FL
24	1		*FRONT BUMPER BRACKET TOP (LH/RH)	O/S Not Necessary / N/S Broken	70.00 FL	*35.00 FL
25	1		*FRONT BUMPER BRACKET (LH/RH)	O/S Not Necessary / N/S Broken	56.00 FL	*28.00 FL
26	2		*FRONT BUMPER RETAINER MOUNTING (LH/RH)	Not Necessary	130.60 FL	*- FL
27	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
28	1		*FRONT BUMPER GRILLE (LH)	Dislodged	186.90 FL	*186.90 FL
29	1		*FRONT BUMPER AIR DUCT (LH)	Not Necessary	153.80 FL	*- FL
30	1		*DAY LIGHT ,LH	Mtg Broken	642.50 FL	*642.50 FL
31	1		*DAY LIGHT WIRE	Not Necessary	585.50 FL	*- FL
32	1		*BUZZER ASSY -PIEZO (LH)	Not Necessary	388.00 FL	*- FL
33	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	1,139.30 FL	*1,139.30 FL
34	2		*HEADLAMP (LH/RH)	Broken	7,974.60 FL	*4,220.60 FL
35	2		*HORN UNIT (LH/RH)	Broken	145.60 FL	*145.60 FL
36	1		*HORN WIRE	Torn	386.70 FL	*386.70 FL
37	1		*RADIATOR INVERTER	Bent / Punctured	884.80 FL	*884.80 FL
38	1		*RADIATOR	Bent / Punctured	710.50 FL	*710.50 FL
39	1		*RADIATOR FAN BLOWER MOTOR ASSY	Broken	1,459.60 FL	*1,459.60 FL
40	2		*RADIATOR AIR GUARD (LH/RH)	Serviceable	152.80 FL	*- FL
41	2		*RADIATOR AIR GUARD UPR (LH/RH)	Serviceable	255.00 FL	*- FL
42	2		*FRONT FENDER (LH/RH)	Dented	981.40 FL	*981.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT FENDER SHIELD (LH/RH) (O/S NOT NECESSARY)	N/S Torn / Broken	329.40 FL	*164.70 FL
44	1		*AIRCON CONDENSER	Bent / Punctured	663.60 FL	*663.60 FL
45	1		*AIRCON SUCTION & LIQUID HOSE	Not Necessary	679.60 FL	*- FL
46	2		*FRT SAFETY BELT (ASSY) (LH/RH)	Activated	1,297.80 FL	*1,297.80 FL
47	2		*REAR SAFETY BELT (ASSY) (LH/RH)	Activated	1,026.40 FL	*1,026.40 FL
48	2		*REAR SAFETY BELT GARNISH COVER (LH/RH)	Broken /Mtg Deformed	796.00 FL	*796.00 FL
49	1		*FRONT WINDSCREEN GLASS	Cracked	1,558.10 FL	*1,558.10 FL
50	1		*FRONT WINDSCREEN MOULDING	Necessary	157.30 FL	*157.30 FL
51	1		*ELECTRONIC CLUTCH ACTUATOR ASSY	Broken	6,345.80 FL	*4,836.50 FL
52	1		*DASHBOARD COMPLETE	Broken	4,724.00 FL	*1,474.00 FL
53	1		*PASSENGER AIR BAG	Activated	2,633.00 FL	*1,951.20 FL
54	1		*STEERING AIRBAG COMPLETE	Activated	1,090.90 FL	*1,090.90 FL
55	1		*AIRBAG CONTROL MODULE	Activated	1,243.70 FL	*1,243.70 FL
56	1		*KNEE CONTROL AIRBAG MODULE ASSY	Activated	578.60 FL	*578.60 FL
57	1		*STEERING ANGLE ASSY	Not Necessary	786.90 FL	*- FL
58	1		*SENSOR ASSY IMPACT -FRT INPACT	Not Necessary	643.90 FL	*- FL
59	2		*AIRBAG SENSOR (LH/RH)	Activated	696.20 FL	*696.20 FL
60	1		*FRONT NUMBER PLATE }	Dislodged	25.00 FS	*45.00 FS
61	1		*FRONT NO PLATE TRIM COVER }	Dislodged	30.00 FS	*- FS
62	1		*COOLANT	Not Necessary	45.00 FS	*- FS
63	1		*INVERTER COOLANT	Not Necessary	65.00 FS	*- FS
64	2		*EMBLEM -BLUE DRIVE (LH/RH)	Necessary	53.20 F	*53.20 FN
65	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
66	1		*FRONT ERP BRACKET	Necessary	30.00 FS	*30.00 FS
67	1		*CLUTCH FLUID	Not Necessary	170.00 FS	*- FS
68	2		*FRONT FENDER APRONG PANEL (LH/RH)	Repair	756.20 FL	*- FL
69	1		*AIR CLEANER HOUSING ASSY	Broken	1,636.50 FL	*1,636.50 FL
70	1		*WIRING -ENGINE	Broken	6,675.00 FL	*6,675.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	62,700.40	48,040.10
- List Item Discount on L Items 20.00/20.00% (S\$)	12,447.24	9,573.18
- Nett Item Discount on N Items 0.00/20.00% (S\$)	0.00	10.64
Total Parts (S\$)	50,253.16	38,456.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,300.00
2	SPRAY PAINTING CHARGE	New	1,600.00	900.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
8	RE-SET FRT ABS SYSTEM	New	200.00	0.00
9	REMOVE/REFIX RADIATOR	New	90.00	50.00
10	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
11	REMOVE/REFIX FUSE BOX	New	120.00	50.00
12	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
13	REMOVE/REFIX ENGINE	New	600.00	0.00
14	REMOVE/REFIX DASHBOARD	New	350.00	150.00
15	REMOVE/REFIX AIR BAG /STEERING WHEEL /DASHBOARD /SEAT }	New	550.00	180.00
16	RE-PROGRAME AIR BAG & SAFETY BELT SYSTEM }	New	550.00	0.00
17	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	550.00	0.00
Gross Labour Cost (\$\$)			7,660.00	2,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >