

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003459/KQY3N2**Date:** 25/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00012622101

**Claimant Vehicle No :** SFD55A **Insured Vehicle No :** CB7227X

Date of Loss: 13/04/2022 Nature of Claim: TP Claim No: SNM22D202558/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SFD55A**

Make & Model: TOYOTA VELLFIRE, 2.4 V (A) Engine No: 2AZF985694

Reg. Date: 30/10/2012 (Man. Year: 2012) Chassis No: ANH208246519

Colour: Metallic Pearl White Odometer: 181906 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,169.40	3,946.32	3,223.08	44.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	1,030.00	750.00	42.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,949.40</b>	<b>4,976.32</b>	<b>3,973.08</b>	<b>44.39</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,950.00</b>		
<b>Nett Amount (\$\$)</b>	<b>8,949.40</b>	<b>3,950.00</b>	<b>4,999.40</b>	<b>55.86</b>

**INSPECTION**

Date of Assignment: 14/04/2022

Date Inspected: 14/04/2022 Inspected At: Poon Siang Seow (HQ)  
160 Sin Ming Drive, #05-13 Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2022)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 V (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFD55A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	861.90 F	*861.90 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	419.85 F	*- FL
3	1		*FRONT BUMPER SPONGE	Cracked	102.00 F	*102.00 FL
4	1		*FRONT BUMPER RETAINER	N/s Distorted	139.80 F	*69.90 FL
5	1		*FRONT HEAD LAMP LEFT	Cracked	2,315.90 F	*2,315.90 FL
6	1		*FRONT HEAD LAMP MOULDING	Serviceable	102.00 F	*- FL
7	1		*FRONT GRILLE	Mtg Cracked	885.90 F	*755.20 FL
8	1		*FRONT FOG LAMP LEFT	Serviceable	381.90 F	*- FL
9	1		*FRONT FOG LAMP COVER	Serviceable	255.90 F	*- FL
10	1		*FRONT FENDER LEFT	Buckled	1,089.65 F	*890.20 FL
11	1		*FRONT FENDER INNER GARNISH	Serviceable	214.60 F	*- FL
12	1		*FRONT BUMPER SENSOR	Scratched	350.00 FS	*200.00 FS
13	1		*NUMBER PLATE	Serviceable	50.00 FS	*- FS
					Sub Total (\$\$)	
					7,169.40	5,195.10
					- List Item Discount on L Items 0.00/25.00% (\$\$)	
					0.00	1,248.78
					Total Parts (\$\$)	
					7,169.40	3,946.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	880.00	600.00
3	RUST PROOFING	New	100.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>1,780.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >