

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003463/GQCE2**Date:** 07/10/2022**REFERENCE**

Insured/Claimant:	TOH WEI LIN	Policy No:	2070030793-01	
Date of Loss:	10/03/2022	Nature of Claim:	OD	Claim No: 1673298544SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD51Z		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX060243
Reg. Date:	27/02/2020 (Man. Year: 2019)	Chassis No:	WAUZZZFVYXK2138776
Colour:	Blue	Odometer:	28826 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$182,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,119.00	11,598.00	11,521.00	49.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,625.00	3,775.00	4,850.00	56.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,744.00	15,373.00	16,371.00	51.57
+ GST 7.00/7.00% (S\$)	2,222.08	1,076.11	1,145.97	51.57
Nett Amount (S\$)	33,966.08	16,449.11	17,516.97	51.57

INSPECTION

Date of Assignment:	14/04/2022		
Date Inspected:	13/04/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,680.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	338.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP -LH	Not Necessary	42.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING EMBLEM -LH	Not Necessary	126.00 FS	*- FS
5	1		*FRONT BUMPER SOILER	Not Necessary	850.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	246.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	651.00 FS	*- FS
8	1		*FRONT BUMPER END CAP LH	Not Necessary	103.00 FS	*- FS
9	2		*LOCKING CLIP	Not Necessary	9.00 FS	*- FS
10	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	43.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	144.00 FS	*- FS
12	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
13	1		*AIR COND STICKER	Not Necessary	22.00 FS	*- FS
14	1		*BONNET	Bent	4,280.00 FS	*3,424.00 FS
15	1		*BONNET ATTACHMENT PARTS	Not Necessary	147.00 FS	*- FS
16	1		*BONNET STICKER -LH	Not Necessary	134.00 FS	*- FS
17	3		*BONNET IMPACT PROTECTION -LH/RH /CENTER	Necessary	93.00 FS	*73.20 FS
18	1		*BONNET LOCK MICRO-SWITCH	Not Necessary	228.00 FS	*- FS
19	1		*HEADLIGHT MOUNTING -LH	Not Necessary	132.00 FS	*- FS
20	1		*HEADLIGHT -LH	Cracked	8,708.00 FS	*6,966.40 FS
21	1		*HEADLIGHT CONTROL UNIT	Not Necessary	813.00 FS	*- FS
22	1		*HEADLIGHT HEAT SINK -LH	Not Necessary	1,222.00 FS	*- FS
23	1		*HEADLIGHT POWER MODULE- LH	Not Necessary	850.00 FS	*- FS
24	1		*HEADLIGHT HOSE-LH	Not Necessary	45.00 FS	*- FS
25	1		*LIFT CYLINDER -LH	Not Necessary	153.00 FS	*- FS
26	1		*LIFT CYLINDER HOSE -LH	Not Necessary	145.00 FS	*- FS
27	1		*FRONT WHEEL SPOILER LH	Not Necessary	181.00 FS	*- FS
28	2		*FRONT WHEEL ARCH COVER -LH/RH	Necessary	1,418.00 FS	*1,134.40 FS
29	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **23,119.00** **11,598.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AHD TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,BONNET AND LHS HEADLIGHT TO REPAIR LHS FRONT FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
4	TO RESPRAY FRONT BUMPER ,FRONT BUMPER LOWER SPOILER ,BONNER ,LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	4,500.00	1,600.00
5	TO APPLY PAINT COATING ON AFFECTED AREA	New	253.00	253.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			8,625.00	3,775.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >