



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 9229M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PROTECTOR,FR,RH (N)	NOT NECESSARY	108.40	-
3	CANOE RIVET FENDER @\$7.70 (N)	NECESSARY	23.10	23.10
14	CLIP FENDER @\$1.40 (N)	NECESSARY	19.60	19.60
1	FENDER-FRONT RH (N)	BUCKLED	587.30	587.30
	LESS 20% DISCOUNT		-147.68	-126.00
			590.72	504.00
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	20.00	20.00
1	ALLOY RIM RH FRONT S/RIM (SN)	SCRATCHED	280.00	280.00
1	185/65R15 CONTL RH FRONT (80%)(SN)	TORN	165.00	132.00
			465.00	432.00
	<u>LABOUR</u>			
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		100.00	100.00
	CHECK WHEEL ALIGNMENT,ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE.		108.00	108.00
	REPAIR FRONT BUMPER AND RENEW RH FRONT FENDER.		800.00	585.00
	S/PAINT FRONT BUMPER AND RH FRONT FENDER.		750.00	500.00
	RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING.		15.00	15.00
	SUPPLY AND RENEW RH FRONT TYRE CONTI 185/65R15 (NPA).	NOT NECESSARY	-	-
			1,773.00	1,308.00
GRAND TOTAL			2,828.72	2,244.00
RECOMMENDED COST OF REPAIRS				2,244.00

Report Ref No. CS/AIS22003474/Gvy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.