

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003475/ENY3M4**Date:** 23/08/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00062992104	
<b>Claimant Vehicle No :</b>	SNC8314K	<b>Insured Vehicle No :</b>	SKW1260H	
Date of Loss:	08/04/2022	Nature of Claim:	TP	Claim No: SNM22D202426/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNC8314K</b>		Engine No:	28291480689304
Make & Model:	MERCEDES-BENZ GLA180, 1.6 (A)		Chassis No:	W1N2477842J337037
Reg. Date:	19/11/2021 (Man. Year: 2021)		Odometer:	6107 km
Colour:	Grey			
Engine Capacity:	1332 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,660.00	1,160.00	41.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,820.00</b>	<b>1,660.00</b>	<b>1,160.00</b>	<b>41.13</b>
<b>+ GST 7.00/7.00% (S\$)</b>	197.40	116.20	81.20	41.13
<b>Nett Amount (S\$)</b>	<b>3,017.40</b>	<b>1,776.20</b>	<b>1,241.20</b>	<b>41.13</b>

INSPECTION

Date of Assignment:	14/04/2022	
Date Inspected:	25/04/2022 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2022)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC8314K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT	New	380.00	380.00
2	REPAIR REAR RIGHT DOOR SHELL	New	1,440.00	480.00
3	RESPRAY REAR RIGHT DOOR	New	1,000.00	800.00
<b>Gross Labour Cost (\$)</b>			<b>2,820.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >