

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003477/KNY3Q2**Date:** 28/09/2022REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00079762200

**Claimant Vehicle  
No :** SLJ5713Z**Insured Vehicle  
No :** SNE5699J

Date of Loss: 11/04/2022

Nature of Claim: TP

Claim  
No: SNM22D202556/C02/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLJ5713Z**

Make &amp; Model: TOYOTA WISH, 1.8 (A)

Engine No: 2ZR1878313

Reg. Date: 16/12/2016 (Man. Year: 2016)

Chassis No: JTDGG20W40J006260

Colour: Metallic Maroon

Odometer: 45450 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 9 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 9 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	737.85	594.90	142.95	19.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	650.00	850.00	56.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,237.85</b>	<b>1,244.90</b>	<b>992.95</b>	<b>44.37</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,000.00</b>		
<b>(\$\$)</b>	2,237.85	1,000.00	1,237.85	55.31
<b>+ GST 7.00/7.00% (\$\$)</b>	156.65	70.00	86.65	55.31
<b>Nett Amount (\$\$)</b>	<b>2,394.50</b>	<b>1,070.00</b>	<b>1,324.50</b>	<b>55.31</b>

INSPECTION

Date of Assignment: 22/04/2022

Date Inspected: 19/04/2022 Inspected At:

Ah Lim Motor Company (AMK)  
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK  
Autopoint  
Singapore 568047

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ5713Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	626.70 FL	*626.70 FL
2	1		*REAR BUMPER REFLECTOR LH	Cut	59.80 FL	*59.80 FL
3	1		*REAR BUMPER UPPER RETAINER LH	Distorted	58.70 FL	*58.70 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	103.50 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
6	1		*REAR BUMPER EXTENSION LH	Repair	87.10 FL	*- FL
					Sub Total (\$\$)	983.80 793.20
					- List Item Discount on L Items 25.00/25.00% (\$\$)	245.95 198.30
					Total Parts (\$\$)	737.85 594.90

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL /REPLACE FUEL TANK ,FIXTURE AND ATTACHMENTS	New	80.00	0.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
4	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD TO KNOCK & REPAIR RR FENDER LH ,TAILLAMP PANEL LH ,REAR END PANEL LH INNER PANEL AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	600.00	200.00
5	TO SPRAY REAR BUMPER ,REAR FENDER LH ,TAILLAMP PANEL LH ,REAR END PANEL LH	New	700.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,500.00</b>	<b>650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >