



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 9909S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT BONNET (WCP)	BUCKLED	480.00	480.00
2	FRT BONNET HINGE (WCP)	NOT NECESSARY	60.00	-
1	FRT BONNET LOCK (WCP)	BENT	38.00	38.00
1	FRT GRILLE ASSY (WCP)	CUT	105.00	105.00
4	FRT GRILLE CLIP (WCP)	NECESSARY	8.00	8.00
1	FRT BUMPER (WCP)	CRACKED	295.00	295.00
2	FRT BUMPER RETAINER (WCP)	NOT NECESSARY	24.00	-
10	FRT BUMPER CLIP (WCP)	NECESSARY	20.00	20.00
1	FRT BUMPER INNER SPONGE (WCP)	CRACKED	85.00	85.00
1	FRT BUMPER REINFORCEMENT (WCP)	BENT	155.00	155.00
1	FRT BUMPER LOWER GRILLE (WCP)	NOT NECESSARY	105.00	-
2	FOG LAMP GARNISH (WCP)	NOT NECESSARY	40.00	-
2	FOG LAMP (NPA)	NOT NECESSARY	-	-
2	HEADLAMP (WCP)	CUT	700.00	700.00
1	HEADLAMP SUPPORT PANEL (WCP)	CRACKED	350.00	350.00
1	AIRCON CONDENSER (WCP)	BENT	220.00	220.00
1	RADIATOR (WCP)	BENT	250.00	250.00
1	RADIATOR FAN ASSY (WCP)	NOT NECESSARY	215.00	-
2	AIRCON SIDE DEFLECTOR (WCP)	CRACKED	36.00	36.00
2	HEADLAMP LOWER BRACKET (WCP)	NECESSARY	36.00	36.00
	COST PLUS 10%		322.20	277.80
			3,544.20	3,055.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT NUMBER PLATE (SN)	CRACKED	40.00	40.00
1	FRT BONNET SEALANT (SN)	NECESSARY	60.00	60.00
			100.00	100.00
<b><u>LABOUR</u></b>				
	WIRE CHECKING.		20.00	20.00
	REMOVE & REFIX AIRCON AND GAS.		100.00	100.00
	LABOUR CHARGE.		750.00	600.00

Report Ref No. CS6/AIS22003480/Gvy3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		750.00	400.00
			1,620.00	1,120.00
	<b>GRAND TOTAL</b>		<b>5,264.20</b>	<b>4,275.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,400.00</b>

Report Ref No. CS6/AIS22003480/Gvy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.