

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003481/AQY3Q2**Date:** 16/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00039042100

Claimant Vehicle No : GBH1437B **Insured Vehicle No :** SLN7132R

Date of Loss: 13/04/2022 Nature of Claim: TP Claim No: SNM22D202561/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH1437B**

Make & Model: NISSAN NV350, 2.5 D Panel Van (M) Engine No: YD25422608A

Reg. Date: 24/01/2018 (Man. Year: 2017) Chassis No: JN1MC2E26Z0008594

Colour: Grey Odometer: 161220 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,907.90	6,246.54	5,661.36	47.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	2,370.00	1,140.00	32.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,417.90	8,616.54	6,801.36	44.11
Approved Total (Overridden) (\$\$)		6,900.00		
(\$\$)	15,417.90	6,900.00	8,517.90	55.25
+ GST 7.00/7.00% (\$\$)	1,079.25	483.00	596.25	55.25
Nett Amount (\$\$)	16,497.15	7,383.00	9,114.15	55.25

INSPECTION

Date of Assignment: 14/04/2022

Date Inspected: 18/04/2022 Inspected At: KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-17 Singapore 417921

Estimated Period of Repair: 8.0 days Repairer: N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Sep 2022)	
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH1437B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CENTER PILLAR LH	Dented	1,386.50 FL	*695.00 FL
2	1		*FRONT BUMPER	Deformed	571.90 FL	*571.90 FL
3	1		*FRONT BUMPER LH FOGLAMP GARNISH	Deformed	120.60 FL	*120.60 FL
4	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Damaged	362.00 FL	*181.00 FL
5	1		*FRONT GRILLE	Not Necessary	527.30 FL	*- FL
6	1		*FRONT GRILLE LOGO EMBLEM	Not Necessary	64.90 FL	*- FL
7	1		*FRONT LH DOOR	Dented	1,071.40 FL	*1,071.40 FL
8	1		*FRONT LH DOOR CHECKER	Not Necessary	42.80 FL	*- FL
9	1		*FRONT LH DOOR HINGE LOWER	Damaged	58.90 FL	*58.90 FL
10	1		*FRONT LH DOOR INNER ARCH WEATHERSTRIP	Not Necessary	176.10 FL	*- FL
11	1		*FRONT LH DOOR INNER TRIM BOARD	Deformed	504.60 FL	*504.60 FL
12	1		*FRONT LH DOOR PILLAR	Repair	1,156.20 FL	*- FL
13	1		*FRONT LH DOOR WEATHERSTRIP	Torn	123.90 FL	*123.90 FL
14	1		*FRONT LH HEADLAMP	Cut	485.30 FL	*485.30 FL
15	1		*FRONT LH LOWER ARM	Bent	228.30 FL	*228.30 FL
16	1		*FRONT LH STEP GARNISH	Deformed	55.90 FL	*55.90 FL
17	1		*FRONT LH TIE ROD END	Not Necessary	142.00 FL	*- FL
18	1		*FRONT LH WHEEL HUB CAP	Cut	161.30 FL	*161.30 FL
19	1		*REAR LH SLIDING DOOR LOWER HINGE	Not Necessary	134.50 FL	*- FL
20	1		*ROCKER PANEL LH	Repair	325.60 FL	*- FL
21	1		*CENTER PILLAR LH 3D STICKER	Necessary	250.00 F	*180.00 FN
22	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 F	*30.00 FN
23	1		*FRONT BUMPER LH FOGLAMP	Not Necessary	311.80 F	*- FN
24	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 F	*- FN
25	1		*FRONT LH 195R15C TYRE	Not Necessary	400.00 F	*- FN
26	1		*FRONT LH DOOR 3D STICKER	Necessary	200.00 F	*80.00 FN
27	1		*FRONT LH DOOR COMPANY STICKER	Necessary	25.00 F	*25.00 FN
28	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 F	*30.00 FN
29	1		*FRONT LH KNOCKLE ARM	Damaged	351.50 F	*351.50 FN
30	1		*FRONT LH KNOCKLE ARM BEARING	Necessary	231.00 F	*231.00 FN
31	1		*FRONT LH SHOCK ABSORBER	Not Necessary	140.50 F	*- FN
32	1		*FRONT LH STABILIZER LINK	Not Necessary	85.60 F	*- FN
33	1		*SET FRONT LH STEP GARNISH CLIPS	Necessary	30.00 F	*30.00 FN
34	1		*FRONT LH WHEEL RIM	Not Necessary	267.50 F	*- FN
35	1		*REAR LH FENDER 3D STICKER	Not Necessary	600.00 F	*- FN
36	1		*REAR LH SLIDING DOOR	Dented	1,325.00 F	*1,325.00 FN
37	1		*REAR LH SLIDING DOOR 3D STICKER	Necessary	600.00 F	*400.00 FN
					Sub Total (\$\$)	12,677.90 6,940.60
					- List Item Discount on L Items 10.00/10.00% (\$\$)	770.00 425.81
					- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00 268.25
					Total Parts (\$\$)	11,907.90 6,246.54

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	80.00	30.00
2	TO REMOVE ,CHARGE FRONT SUSPENSION PARTS ,ABSORBER ,LOWER ARM ,KNOCKLE ARM ,WHEEL BEARING ,BEARING HUB DRIVE SHAFT, ANTI-ROLL BAR ,TOP-ARM AND STEERING RACK AND PINION	New	350.00	220.00
3	TO ROAD TEST DRIVING ,CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
4	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,RAILING CHANNEL TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	160.00	80.00
5	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTEST TO THE ACCIDENT	New	1,400.00	900.00
6	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,300.00	1,000.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (\$\$)			3,510.00	2,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >