

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003486/KQY3M4**Date:** 04/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004832101

Claimant Vehicle No : SLE3777D **Insured Vehicle No :** SMQ6132U

Date of Loss: 08/04/2022 Nature of Claim: TP Claim No: SNM22D202493/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE3777D**

Make & Model: KIA OPTIMA, 2.0 (A) Engine No: G4NDFH092295

Reg. Date: 20/07/2016 (Man. Year: 2015) Chassis No: KNAGU411MG5034612

Colour: Metallic Pearl White Odometer: 178026 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,384.90	3,566.10	8,818.80	71.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	440.00	2,060.00	82.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,884.90	4,006.10	10,878.80	73.09
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	14,884.90	3,000.00	11,884.90	79.85
+ GST 7.00/7.00% (\$\$)	1,041.94	210.00	831.94	79.85
Nett Amount (\$\$)	15,926.84	3,210.00	12,716.84	79.85

INSPECTION

Date of Assignment: 14/04/2022

Date Inspected: 28/04/2022 Inspected At: Fulco Autocare Pte Ltd (HQ)
176 SIN MING DRIVE #03-02 SIN MING
AUTOCARE
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2022)
Parts:	143	KIA OPTIMA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE3777D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,583.00 FL	*- FL
2	1		*BONNET LOCK	Repair	139.00 FL	*- FL
3	1		*BONNET BOTTOM LOCK ASSY	Repair	58.00 FL	*- FL
4	1		*BONNET LOCK SENSOR	Serviceable	139.00 FL	*- FL
5	1		*FRONT FENDER O/S	Repair	920.00 FL	*- FL
6	1		*FRONT FENDER COWLING O/S	Serviceable	189.00 FL	*- FL
7	1		*HEADLAMP O/S	Cut	2,996.00 FL	*2,546.00 FL
8	1		*HEADLAMP LOWER BRACKET O/S	Serviceable	168.00 FL	*- FL
9	1		*FRONT BUMPER	Buckled	1,286.00 FL	*531.00 FL
10	1		*FRONT BUMPER TOW COVER	Serviceable	45.00 FL	*- FL
11	1		*FRONT BUMPER KIA EMBLEM	Necessary	76.00 FL	*76.00 FL
12	2		*FRONT BUMPER SIDE RETAINER	Serviceable	96.00 FL	*- FL
13	2		*FRONT BUMPER BRACKET	Serviceable	88.00 FL	*- FL
14	1		*FRONT BUMPER GRILLE	Serviceable	457.00 FL	*- FL
15	1		*FRONT BUMPER GRILLE CHROME TRIM	Serviceable	289.00 FL	*- FL
16	1		*FRONT BUMPER LOWER GRILLE	Cracked	394.00 FL	*241.00 FL
17	1		*FRONT BUMPER SIDE CHROME O/S	Scratched	293.00 FL	*62.00 FL
18	1		*WASHER NOZZLE O/S	Cracked	412.00 FL	*245.00 FL
19	1		*WASHER NOZZLE COVER O/S	Missing	72.00 FL	*72.00 FL
20	1		*WASHER NOZZLE BRACKET O/S	Serviceable	48.00 FL	*- FL
21	1		*FRONT BUMPER SPONGE	Cracked	218.00 FL	*116.00 FL
22	1		*FRONT BUMPER REINFORCEMENT	Serviceable	689.00 FL	*- FL
23	1		*ENGINE UNDER COWLING	Serviceable	280.00 FL	*- FL
24	1		*FRONT BUMPER SENSOR HARNESS	Serviceable	521.00 FL	*- FL
25	1		*WASHER TANK	Serviceable	187.00 FL	*- FL
26	1		*WASHER TANK MOTOR	Serviceable	213.00 FL	*- FL
27	1		*FRONT SUPPORT FRAME	Serviceable	995.00 FL	*- FL
28	10		*BONNET INSULATOR CLIPS	Not Necessary	55.00 FS	*- FS
29	8		*FRONT FENDER COWLING CLIPS O/S	Not Necessary	44.00 FS	*- FS
30	12		*FRONT BUMPER CLIPS	Necessary	66.00 FS	*66.00 FS
31	8		*ENGINE UNDER COWLING CLIPS	Not Necessary	44.00 FS	*- FS
32	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
33	2		*FRONT BUMPER SENSOR	Serviceable	500.00 FS	*- FS
34	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,670.00	3,955.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,285.10	388.90
Total Parts (\$\$)	12,384.90	3,566.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTIONS. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,200.00	200.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	20.00
3	TO REMOVE AND REFIT RADIATOR TO FACILITATE REPAIR. TO PERFORM PRESSURE TEST AND CHECK COOLING SYSTEM FUNCTIONALITY	New	150.00	0.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL	New	1,000.00	220.00
5	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIRS	New	100.00	0.00
Gross Labour Cost (\$)			2,500.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >