

ASS. REC. BY:

REF:

C72 / 220034861K943

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Fulco

of

3086

Insured:

Policy No.

Claims No.

SNM210202493/002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1. B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

81E3777D

Yr Regn:

07, 16

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Opina K c.c

1999

Colour

R. P. White

A/C: Insured / Std / NI / NA

Sp. Reading

178826

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAGU 411MG 5034812

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

8/4/22

D.O.I.

28/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Est not ready

1315

61 Lm & 3000 Ched @ 11854.70, 80%

07/06/22 @ 12.36pm revised to Adeline Chng via Messenger.

Date/Time, File Pass to?

11/7/2022

Date/Time, File Return to?

2)

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. \$

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format:

MER-TP

Lump Sum / I.B.A. (\$)

3000

Repair Estimate


Fulco Autocare Pte Ltd

176 Sin Ming Drive #03-02 Sin Ming Autocare Singapore 575721
Tel: (65) 6552 0302 Fax: (65) 6552 0780 Email: admin@fulcoautocare.com

Not Authorised
11 Rm @ 3000h
Paying After Repair
3 days

Make/Model: KIA OPTIMA K5
Engine/Chassis No.: KNAGU411MG5034612
Date of accident:
Damaged area: O/S Front

Date: 28/04/2022
Claim Type: TP
VRN: SLE3777D



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bonnet	1	\$ 1,583.00	\$ 1,583.00	X
2	Bonnet lock	1	\$ 139.00	\$ 139.00	X
3	Bonnet bottom lock assy	1	\$ 58.00	\$ 58.00	X
4	Bonnet lock sensor	1	\$ 139.00	\$ 139.00	X
5	Front fender o/s	1	\$ 920.00	\$ 920.00	X
6	Front fender cowl o/s	1	\$ 189.00	\$ 189.00	X
7	Headlamp o/s 2346	1	\$ 2,996.00	\$ 2,996.00	✓
8	Headlamp lower bracket o/s	1	\$ 168.00	\$ 168.00	X
9	Front bumper 531.00	1	\$ 1,286.00	\$ 1,286.00	✓
10	Front bumper tow cover	1	\$ 45.00	\$ 45.00	X
11	Front bumper "KIA" emblem	1	\$ 76.00	\$ 76.00	✓
12	Front bumper side retainer	2	\$ 48.00	\$ 96.00	X
13	Front bumper bracket	2	\$ 44.00	\$ 88.00	X
14	Front bumper grille	1	\$ 457.00	\$ 457.00	X
15	Front bumper grille chrome trim	1	\$ 289.00	\$ 289.00	X
16	Front bumper lower grille 241	1	\$ 394.00	\$ 394.00	✓
17	Front bumper side chrome o/s 62	1	\$ 293.00	\$ 293.00	✓
18	Washer nozzle o/s 245	1	\$ 412.00	\$ 412.00	✓
19	Washer nozzle cover o/s	1	\$ 72.00	\$ 72.00	✓
20	Washer nozzle bracket o/s	1	\$ 48.00	\$ 48.00	X
21	Front bumper sponge 116	1	\$ 218.00	\$ 218.00	✓
22	Front bumper reinforcement	1	\$ 689.00	\$ 689.00	X
23	Engine under cowl	1	\$ 280.00	\$ 280.00	X
24	Front bumper sensor harness	1	\$ 521.00	\$ 521.00	X
25	Washer tank	1	\$ 187.00	\$ 187.00	X
26	Washer tank motor	1	\$ 213.00	\$ 213.00	X
27	Front support frame	1	\$ 995.00	\$ 995.00	X
Subtotal				\$ 12,851.00	
List discount				10.00%	
Total				\$ 11,565.90	

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet insulator clips	10	\$ 5.50	\$ 55.00
2	Front fender cowling clips o/s	8	\$ 5.50	\$ 44.00
3	Front bumper clips	12	\$ 5.50	\$ 66.00
4	Engine under cowling clips	8	\$ 5.50	\$ 44.00
5	Radiator coolant	1	\$ 60.00	\$ 60.00
6	Front bumper sensor	2	\$ 250.00	\$ 500.00
7	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 819.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and refit radiator to facilitate repair. To perform pressure test and check cooling system functionality.	0.75	\$ 150.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
5	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,500.00

Estimate Grand Total	\$ 14,884.90
----------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



THE FLAME TREE MEDICAL CENTRE
 225, UPPER THOMSON ROAD, SINGAPORE 574357
 TEL: 6451 2818 FAX: 6452 3800

No. 43349

Date: 8/4/22

MEDICAL CERTIFICATE

This is to certify that Mr / ~~Mdm~~ / Ms Koh Shi Yang Nathanael

☒ is unfit for duty / to attend school for three (3) days
 on / from 8/4/22 to 10/4/22 inclusive.

☐ is fit for light duty from _____ to _____ inclusive.

☐ is fit for duty

☐ Time chit Time in _____

DR KARTIKA HANAFI-TAY
 MBBS (SINGAPORE)
THE FLAME TREE MEDICAL CENTRE
 MCR : 06813F

Remarks: RTA

* The certificate is not valid for absence from court or
 other judicial proceedings unless specifically stated.

[Signature]
 Issued By