



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 7555A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	NOT NECESSARY	1,445.00	-
2	REAR BUMPER SIDE BRACKET @\$135.20	NOT NECESSARY	270.40	-
1	TAIL LAMP	CRACKED	852.00	725.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,954.00	-
1	REAR FENDER R/H COWLING	NOT NECESSARY	144.00	-
1	FRONT R/H DOOR	DENTED	1,623.00	1,623.00
1	FRONT RH DOOR INNER LOCK	DAMAGED	590.00	385.00
1	FRONT R/H DOOR TOP MOULDING	NOT NECESSARY	168.20	-
1	FRONT RH DOOR GEAR MOTOR ASSY	DAMAGED	852.00	540.00
1	FRONT R/H DOOR OUTER HANDLE	NOT NECESSARY	165.20	-
1	FRONT R/H DOOR GLASS RUBBER	NOT NECESSARY	210.00	-
1	FRONT R/H DOOR TOP MOULDING RUBBER	NOT NECESSARY	155.20	-
1	FRONT R/H DOOR INNER RUBBER	NECESSARY	218.20	218.20
1	FRONT R/H DOOR INNER TRIM BOARD	NOT NECESSARY	1,480.00	-
1	REAR RH DOOR	DENTED	1,623.00	1,623.00
1	REAR RH OUTER HANDLE	NOT NECESSARY	165.20	-
1	REAR RH DOOR TOP MOULDING	NOT NECESSARY	168.20	-
1	REAR RH DOOR INNER RUBBER	NECESSARY	215.20	215.20
1	REAR R/H KNOCKING ARM	NOT NECESSARY	854.00	-
1	REAR R/H WHEEL BEARING	NOT NECESSARY	226.00	-
1	REAR R/H LOWER ARM	NOT NECESSARY	472.00	-
1	REAR RH RIM	NOT NECESSARY	750.00	-
1	REAR RH TYRE	NOT NECESSARY	550.00	-
	LESS 10% DISCOUNT		-	-532.94
			15,150.80	4,796.46
	<u>LABOUR</u>			
	TO REMOVE & RE-FIX REAR UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO CHECK WHEEL ALIGNMENT.		120.00	-
	TO REMOVE & RE-FIX CUSHION.		150.00	150.00
	TUFF KOTE.		150.00	60.00

Report Ref No. CS/SGK22003489/Aqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,200.00	700.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,200.00	600.00
			3,200.00	1,510.00
GRAND TOTAL			18,350.80	6,306.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/SGK22003489/Aqy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.