

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22003494/EPA3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900260562
Claimant Vehicle No :	SHB779G	Insured Vehicle No :	SMR692D
Date of Loss:	06/04/2022	Nature of Claim:	TP
		Claim No:	2362991731SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB779G		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR6557510
Reg. Date:	15/01/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U905766835
Colour:	Maroon	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,639.85	2,562.43	19,077.42	88.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,742.00	1,670.00	3,072.00	64.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,381.85	4,232.43	22,149.42	83.96
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	26,381.85	3,700.00	22,681.85	85.98
+ Car Rental (12.5 x S\$66.00/day) (S\$)		825.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,532.00		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment:	14/04/2022	
Date Inspected:	14/04/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER FRT/RH (DISC 25%)	Dented	723.40 F	*542.55 F
2	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
3	1		*FENDER LINER FRT/RH (DISC 25%)	Crushed	171.70 F	*128.78 F
4	1		*DOOR FRT/RH (DISC 25%)	Dented	894.40 F	*670.80 F
5	1		*BUMPER SUPPORT F/RH (DISC 25%)	Broken	76.40 F	*57.30 F
6	1		*FENDER PROTECTOR FRT/RH SIDE (DISC 25%)	Bent	113.90 F	*85.43 F
7	1		*HINGE LOWER RHF,DOOR (DISC 25%)	Bent	90.10 F	*67.58 F
8	1		*HINGE UPPER RHF,DOOR (DISC 25%)	Broken	80.50 F	*60.38 F
9	1		*HEAD LAMP RH (DISC 10%)	Broken	945.20 F	*850.68 F
10	1		*STICKER STRIDES TAXI (DOOR)(SN)	Necessary	60.00 F	*60.00 F
11	1		*BUMPER CLIPS	Not Necessary	1.61 F	*- F
12	1		*BUMPER SUPPORT F/RH	Not Necessary	76.40 F	*- F
13	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F
14	1		*FOG LAMP RH	Not Necessary	295.20 F	*- F
15	1		*BRACKET,FR TURN UPPER RH	Not Necessary	24.40 F	*- F
16	1		*BRACKET,FR TURN	Not Necessary	58.20 F	*- F
17	1		*BRACKET,FR TURN LOWER RH	Not Necessary	26.00 F	*- F
18	1		*LENS & BODY,FR TURN RH	Not Necessary	511.80 F	*- F
19	1		*UNDER COVER SIDE/RH	Not Necessary	46.10 F	*- F
20	1		*UNDER COVER CENTER	Not Necessary	448.30 F	*- F
21	1		*HOOD PANEL	Not Necessary	748.10 F	*- F
22	1		*HOOD HINGE LH	Not Necessary	55.90 F	*- F
23	1		*HOOD HINGE RH	Not Necessary	55.90 F	*- F
24	1		*HEAD LAMP RH	Not Necessary	945.20 F	*- F
25	1		*WIPER WASHER INLET	Not Necessary	36.90 F	*- F
26	1		*WIPER WASHER JAR	Not Necessary	180.10 F	*- F
27	1		*MOTOR NO.1 WIPER WASHER JAR	Not Necessary	239.00 F	*- F
28	1		*MOTOR NO.2 WIPER WASHER JAR	Not Necessary	240.00 F	*- F
29	1		*FENDER PROTECTOR FRT/RH SIDE	Not Necessary	113.90 F	*- F
30	1		*FENDER SEAL TO COWL SIDE RH	Not Necessary	15.20 F	*- F
31	1		*FENDER LINER PAD,FR WHEEL,RH	Not Necessary	49.30 F	*- F
32	1		*FENDER APRON SUB FRT/RH	Not Necessary	637.80 F	*- F
33	1		*TYRE	Not Necessary	126.74 F	*- F
34	1		*MOULDING BODY,RH	Not Necessary	673.60 F	*- F
35	1		*SHOCK ABSORBER FRT/RH	Not Necessary	394.20 F	*- F
36	2		*SHOCK ABSORBER MOUNTING FRT RH/LH	Not Necessary	193.80 F	*- F
37	2		*SHOCK ABSORBER BEARING FRT RH/LH	Not Necessary	34.00 F	*- F
38	2		*STABILIZER BAR LINK FRT/RH/LH	Not Necessary	195.00 F	*- F
39	1		*SIDE CHASSIC BRACE FRT/RH	Not Necessary	103.80 F	*- F
40	1		*STABILIZER BAR FRT	Not Necessary	348.80 F	*- F
41	1		*STEERING KNUCKLE RH FRT	Not Necessary	580.80 F	*- F
42	1		*WHEEL HUB FRT	Not Necessary	549.70 F	*- F
43	1		*LOWER ARM FRT/RH	Not Necessary	625.90 F	*- F
44	1		*JOINT ASSY,LWR BALL	Not Necessary	195.60 F	*- F
45	1		*TIE ROD END RH	Not Necessary	159.30 F	*- F
46	1		*STEERING RACK ASSY	Not Necessary	1,597.50 F	*- F
47	1		*CROSS MEMBER FRT	Not Necessary	2,497.50 F	*- F
48	1		*SIDE CHASSIC FRT/RH	Not Necessary	173.50 F	*- F
49	1		*SIDE CHASSIC BRACE FRT/RH	Not Necessary	103.80 F	*- F
50	1		*HINGE LOWER RHF,DOOR	Not Necessary	90.10 F	*- F
51	1		*HINGE UPPER RHF,DOOR	Not Necessary	80.50 F	*- F
52	1		*CHECK ASSY,FR DOOR	Not Necessary	150.30 F	*- F
53	1		*DOOR BELT FRT/RH	Not Necessary	69.20 F	*- F
54	1		*DOOR REGULATOR SUB-ASSY,FRT/REAR RH	Not Necessary	224.80 F	*- F
55	1		*DOOR REGULATOR MOTOR FRONT RH	Not Necessary	947.80 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*MOULDING,FR DOOR WINDOW RH	Not Necessary	53.70 F	*- F
57	1		*MIRROR ASSY,RH	Not Necessary	1,307.10 F	*- F
58	1		*COVER,OUTER MIRROR,RH	Not Necessary	107.40 F	*- F
59	1		*BUMPER FRT	Repair	482.00 F	*- F
60	1		*WHEEL DISC	Repair	1,484.20 F	*- F
F=Franchise part.						
					Total Parts (S\$)	21,639.85 2,562.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,214.00	600.00
2	SPRAY PAINT	New	2,812.00	850.00
3	TOWING CHARGE	New	56.00	40.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	30.00
5	TO WASH AND VACUUM	New	60.00	0.00
6	TO REPLACE SUNDRY PARTS	New	120.00	20.00
7	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	120.00	20.00
8	TO DO WHEEL ALIGNMENT/TYRE BALANCING	New	120.00	60.00
9	TO TRANSFER DOOR MECHANISM	New	120.00	50.00
Gross Labour Cost (S\$)			4,742.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >