

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003497/UPA3Q2**Date:** 14/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800147376
Claimant Vehicle No :	SMN8749T	Insured Vehicle No :	SJL9242C
Date of Loss:	15/04/2022	Nature of Claim:	TP
		Claim No:	3451040368SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN8749T	Engine No:	2NR5387889
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3501186935
Reg. Date:	30/08/2019 (Man. Year: 2019)	Odometer:	249770 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,188.60	8,112.64	15,075.96	65.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,880.00	3,320.00	1,560.00	31.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,068.60	11,432.64	16,635.96	59.27
Approved Total (Overridden) (S\$)		9,100.00		
(S\$)	28,068.60	9,100.00	18,968.60	67.58
+ GST 7.00/7.00% (S\$)	1,964.80	637.00	1,327.80	67.58
Nett Amount (S\$)	30,033.40	9,737.00	20,296.40	67.58
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,239.00		
Global Sum Settlement (S\$)		10,230.00		

INSPECTION

Date of Assignment:	18/04/2022		Fastech Auto Pte Ltd (HQ)
Date Inspected:	18/04/2022	Inspected At:	1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
			Singapore 417883
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	665.30 F	*525.80 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*HEADLAMP N/S	Not Necessary	1,801.00 F	*- FL
4	1		*FRONT FENDER N/S	Badly Dented	751.10 F	*577.10 FL
5	1		*FRONT FENDER INNER SHIELD N/S	Torn	228.30 F	*166.80 FL
6	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
7	1		*FRONT FENDER INNER VERTCAL GARNISH N/S	Deformed	121.30 F	*121.30 FL
8	1		*FRONT SPORT RIM N/S	Warped	1,801.30 FS	*600.00 FS
9	1		*FRONT LOWER ARM N/S	Bent	662.40 F	*408.20 FL
10	1		*FRONT KNUCKLE ARM N/S	Bent	588.50 F	*422.30 FL
11	1		*FRONT KNUCKLE ARM BEARING N/S	Necessary	225.30 F	*205.50 FL
12	1		*FRONT SHOCK ABSORBER N/S	Bent	499.50 F	*415.20 FL
13	1		*FRONT DRIVE SHAFT N/S	Not Necessary	1,288.30 F	*- FL
14	1		*FRONT DOOR N/S	Badly Dented	1,455.20 F	*1,012.30 FL
15	1		*SET FRONT DOOR FRAME BLACK STICKER N/S	Necessary	85.00 F	*85.00 FL
16	1		*FRONT DOOR INNER RUBBER N/S	Necessary	199.30 F	*199.30 FL
17	1		*FRONT DOOR INNER TRIM BOARD N/S	Deformed / Torn	945.20 F	*611.20 FL
18	1		*FRONT DOOR INNER LOCK N/S	Shorted / Damaged	385.50 F	*345.20 FL
19	1		*FRONT DOOR GLASS OUTER MOULDING N/S	Not Necessary	112.80 F	*- FL
20	1		*FRONT DOOR GLASS REGULATOR N/S	Bent	345.50 F	*265.10 FL
21	1		*FRONT DOOR GLASS REGULATOR MOTOR N/S	Shorted	645.20 F	*390.00 FL
22	2		*FRONT DOOR HINGE N/S	Bent	190.00 F	*190.00 FL
23	1		*FRONT DOOR CHECKER N/S	Torn off	121.00 F	*121.00 FL
24	1		*FRONT DOOR OUTER PILLAR N/S	Repair	665.20 F	*- FL
25	1		*ROCKER PANEL N/S	Repair	845.20 F	*- FL
26	1		*REAR DOOR N/S	Dented / Bent	1,485.30 F	*1,012.25 FL
27	1		*SET REAR DOOR FRAME BLACK STICKER N/S	Necessary	68.00 F	*68.00 FL
28	1		*REAR DOOR INNER LOCK N/S	Serviceable	385.20 F	*- FL
29	1		*REAR DOOR INNER TRIM N/S	Not Necessary	855.20 F	*- FL
30	1		*REAR DOOR GLASS OUTER MOULDING N/S	Not Necessary	112.80 F	*- FL
31	1		*REAR FENDER N/S	Badly Dented	971.30 F	*941.30 FL
32	1		*REAR FENDER UNDER SHIELD N/S	Torn	122.80 F	*108.50 FL
33	1		*SET REAR FENDER UNDER SHIELD CLIPS N/S	Necessary	30.00 F	*30.00 FL
34	1		*REAR WINDSCREEN MOULDING	Necessary	168.50 F	*168.50 FL
35	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 F	*50.00 FL
36	1		*REAR BUMPER	Torn	662.30 F	*557.20 FL
37	1		*REAR BUMPER SIDE RETAINER N/S	Bent	69.80 F	*69.80 FL
38	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
39	1		*TAILLAMP N/S	Not Necessary	481.20 F	*- FL
40	1		*REAR SPORT RIM N/S	Cut	1,801.30 FS	*600.00 FS
41	1		*REAR WHEEL HUB BEARING N/S	Not Necessary	485.00 F	*- FL
42	1		*CENTRE PILLAR N/S	Repair	662.50 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,188.60	10,416.85
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,304.21
Total Parts (\$\$)	23,188.60	8,112.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	120.00
4	TO DISMANTLE & REFIX FUEL TANK	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO DISMANTLE & REFIX BOTH N/S DOOR MECHANISM	New	180.00	120.00
7	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	180.00	120.00
8	TO RESET & DIAGNOSTIC SYSTEM	New	180.00	50.00
9	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
10	TO SPRAY RUST PROOFING	New	150.00	120.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	1,100.00
12	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,400.00
Gross Labour Cost (\$\$)			4,880.00	3,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >