

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No. 199007190R GST Reg. No. 19-9007190-R | | | | | |
|---|--|--|-----------------|------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
| | AUTO & GENERAL | L INSURANCE (S) PL | R | Ref: | CS/AGI22003499/Kqy3m4 | |
| | (BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924 | INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE | D | ate: | 06/06/2022 | |
| | | | C | ode: | AGI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLQ 8936R | Veh. Inspected | | SFV 5955A | |
| | Policy No. | P10413667R01 | Coverage (\$) | | 0.00 | |
| | Claim No. | C10014733/JM | Excess (\$) | | 0.00 | |
| | Assign From | SHAFAWATI MD RABU | Assign Date | | 18/04/2022 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | MERCEDES B180 (A) | c.c | | 1595 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2014 | |
| | Chassis No. | WDD2462422J271905 | Colour | | METALLIC BLACK | |
| | Odometer | 116958 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | |
| | General | GOOD | | | | |
| 3. | Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/55R16 | MICHELIN | | 7 mm | |
| | L/H Front Tyre | 205/55R16 | MICHELIN | | 7 mm | |
| | R/H Rear Tyre | 205/55R16 | MICHELIN | | 7 mm | |
| | L/H Rear Tyre | 205/55R16 | MICHELIN | | 7 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND FRONT PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 13/04/2022 | Inspection Date | | 18/04/2022 | |
| | Survey held at | READY AUTO CARE PL | | | | |
| | | BLK 10 #03-06, AMK AUTOPOINT, ANG MO KIO AVE 5, INDUSTRIAL PARK 2A, SINGAPORE 568047 | | | | |
| 5a. | | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |

9 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: