



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 4964Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT	1,480.00	1,047.80
2	FRONT BUMPER SIDE RETAINER @\$145.00	NECESSARY	290.00	82.00
1	FRONT BUMPER FOG LAMP LH	BROKEN	320.00	294.00
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	1,445.55	-
1	FRONT FENDER INNER COWLING LH	NOT DAMAGED	192.00	-
1	HEADLAMP LH	CUT	2,393.00	2,119.00
1	HEADLAMP LOWER BRACKET LH	BROKEN	189.00	48.00
1	FRONT SHOCK ABSORBER LH	NOT DAMAGED	655.00	-
1	FRONT KNUCKLE ARM LH	NOT DAMAGED	1,085.30	-
1	FRONT KNUCKLE ARM BEARING LH	NOT DAMAGED	562.00	-
1	FRONT LOWER ARM LH	NOT DAMAGED	580.00	-
1	FRONT TRUST ARM LH	NOT DAMAGED	577.00	-
	LESS 5% DISCOUNT		-488.44	-179.54
			9,280.41	3,411.26
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
4	FRONT BUMPER PARKING SENSOR SEAL @\$48.00 (SN)	NECESSARY	192.00	60.00
1	FRONT FENDER SEALANT (SN)	NOT DAMAGED	100.00	-
1	FRONT FENDER INNER COWLING CLIPS (SN)	NOT DAMAGED	60.00	-
2	FRONT ALLOY RIM LH @\$980.00 (SN)	NOT DAMAGED	1,960.00	-
2	FRONT TYRE LH @\$530.00 (SN)	NOT DAMAGED	1,060.00	-
			3,512.00	90.00
<u>LABOUR</u>				
	R&R FRONT BUMPER PARKING SENSOR.		100.00	60.00
	R&R FRONT UNDER CARRIAGE.	NOT NECESSARY	250.00	-
	R&R FRONT TYRE AND BALANCING.	NOT NECESSARY	100.00	-
	CHECK WIRING.	NOT NECESSARY	100.00	-
	UOHOLSTERY.	NOT NECESSARY	300.00	-

Report Ref No. CS/AGI22003502/Bty3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	DIAGNOTIC RESET FAULT CODE.		300.00	120.00
	CONDUCT WATER LEAK TEST.	NOT NECESSARY	180.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		1,200.00	800.00
	RUST PROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		1,200.00	400.00
			3,930.00	1,380.00
GRAND TOTAL			16,722.41	4,881.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CS/AGI22003502/Bty3n2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.