



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 9204R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	BUCKLED	1,477.32	1,362.45
1	REAR BUMPER LIP SPOILER	DENTED / CUT	400.54	400.54
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	588.75	-
1	REAR BUMPER RETAINER / LH	SERVICEABLE	90.97	-
1	REAR BUMPER RETAINER / RH	SERVICEABLE	90.97	-
1	REAR BUMPER RETAINER (CENTRE)	SERVICEABLE	250.54	-
1	REAR TAILEND PANEL	TO REPAIR SEE LABOUR	300.47	-
1	REAR TAILEND PANEL (LOWER)	TO REPAIR SEE LABOUR	366.75	-
1	REAR TAILEND INNER GARNISH	SERVICEABLE	366.75	-
1	REAR SILENCER - LEFT	TO REPAIR SEE LABOUR	717.00	-
1	REAR SILENCER OUTER CHROME FINISHER / LH	SERVICEABLE	388.75	-
	LESS 10% DISCOUNT		-	-176.30
			5,038.81	1,586.69
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR TAILEND PANEL TEROSTAT SEALANT (SN)	NOT NECESSARY	54.20	-
1	REAR TAILEND INNER GARNISH CLIPS (SN)	NOT NECESSARY	12.00	-
1	REAR EMBLEM 'VWK' (SN)	NOT NECESSARY	180.54	-
1	REAR EMBLEM 'GOLF' (SN)	NOT NECESSARY	121.50	-
1	REAR EMBLEM 'TSI' (SN)	NOT NECESSARY	98.60	-
1	REAR EMBLEM 'BLUEMOTION' (SN)	NOT NECESSARY	111.15	-
1	REAR NO PLATE (EMBOSS) (SN) }	BENT	35.00	45.00
1	REAR NO PLATE HOLDER (SN) }		25.00	-
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
5	REAR BUMPER FASTENER @\$5.50 (SN)	NECESSARY	27.50	27.50
5	REAR BUMPER EXTENSION FASTENER @\$5.50 (SN)	NOT NECESSARY	27.50	-
			942.99	72.50



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.	NOT NECESSARY	120.00	-
	TO CHECK WATER SEEPAGE.	NOT NECESSARY	60.00	-
	TO CHECK REAR WIRING FUNCTION.		35.00	10.00
	TO REMOVE & REPLACED / REPAIRED AFFECTED RIM.	NOT NECESSARY	150.00	-
	TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS.		120.00	50.00
	TO REPAIR, PANEL BEAT, ALIGN ON REAR AFFECTED AREA, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE ABOVE. INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM, REAR TAILEND PANEL, REAR TAILEND PANEL (LOWER) AND REAR SILENCER - LEFT.		800.00	280.00
	TO SPRAY ON REAR BUMPER, END PANEL, SENSOR & AFFECTED REAR TAILGATE USING 2K PAINT.		800.00	450.00
			2,085.00	790.00
	<b>GRAND TOTAL</b>		<b>8,066.80</b>	<b>2,449.19</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,449.19</b>

Report Ref No. CS/AGI22003503/Kny3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.