

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 7499S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	1,267.00	1,267.00
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER BEAM	DENTED	539.00	539.00
2	REAR BUMPER TOW COVER @\$25.00	O/S CUT / N/S NOT NECESSARY	50.00	25.00
2	REAR BUMPER SIDE RETAINER @\$41.00	NOT NECESSARY	82.00	-
1	BOOT LID	NOT NECESSARY	1,115.00	-
1	BOOT LID RUBBER	NOT NECESSARY	136.00	-
2	BOOT LID LAMP @\$769.00	NOT NECESSARY	1,538.00	-
1	BOOT LID BADGE - MAZDA 6	NOT NECESSARY	41.00	-
1	BOOT LID - SKYACTIV	NOT NECESSARY	75.00	-
1	BOOT LID INNER TRIM	NOT NECESSARY	182.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	701.00	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	123.00	-
2	TAIL LAMP @\$1593.00	NOT NECESSARY	3,186.00	-
2	REAR BUMPER REFLECTOR LAMP @\$260.00	NOT NECESSARY	520.00	-
	LESS 20% DISCOUNT		-1,921.00	-376.20
			7,684.00	1,504.80
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,100.00	500.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		80.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	120.00	-
			2,370.00	970.00
	GRAND TOTAL		10,054.00	2,474.80

Report Ref No. CS/AGI22003507/Uvy3n2





- 1	RECOMMENDED COST OF REPAIR SUM		2.200.00

Report Ref No. CS/AGI22003507/Uvy3n2

\*NOTE: NEW PARTS REPLACEMENT

CHUA KANG SENG

**Licensed Appraiser**