HONDA AH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad) Service and Body Repair Tel: +65 6841 3838

For 24-hours Roadside Assistance, Call 98203838 Website: www.honda.com.sg QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

Customer

Item

ROSLIN

: AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER SINGAPORE 068811

Registration No : SMD2876B Chassis No

Model Owner's Name

: JHMRU1830GX204155 : HRV LX-SIN CVT YM 2016 : HAMISH JOSEPH WINSTANLEY

Ins Policy No. Date of Accident

: 8/4/2022

Document No.

Date

: SQT22000962

: 9. Apr 2022

: WZA006 Customer No. : NG SIN HAI Svc Advisor : L15B4534155 **Engine No** 9. Apr 2022 10:31:59 AM

Date | Time Surveyor Name

110.00

220.00

120.00

120.00

120.00

220.00

650 00

650.00

650.00

650.00

120.00

5500.00

3200.00

450.00

650.00

650.00

650.00

1

1 650

Survey Date Authorisation Date

> 0% GST Amount

> > 7.70

15.40

8.40

8.40

8.40

15.40

45.50

45.50

45.50

8.40

385.00

224.00

31.50

45.50

45.50

45.50

Amount

117.70

235.40

128.40

128.40

128.40

235.40

695.50

695.50

695.50

695.50

128.40

5885.00

3424.00

481.50

695.50

695.50

695.50

Description TP DIRECT SETTLEMENT (J/NO:

OWNER:

OWNER INSURER:

ACC DATE: SURVEYED BY:

DATE: REF NO: TP INSURER:

TP VEH:

SUNDRIES

| BA02R | REMOVE & RENEW REVERSE SENSORS-4 PCS (N) |
|---------|---|
| BOJSE | BODY JOINT SEALANT REAR END PANEL |
| BOJSE | BODY JOINT SEALANT REAR FLOOR PANEL |
| BOJSE | BODY JOINT SEALANT TAILGATE |
| BML02I | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER |
| BMF00D | RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N) |
| BMI02D | REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK |
| BKTG02B | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. |

BKTG02R REMOVE & INSTALL RR. WINDSCREEN.(N) BG02D WINDSCREEN DAM KIT. BODAMKIT

CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN BKRP02M SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. BP06R REMOVE & RENEW RR FLOOR INSULATOR.(N) **BKOTOOR**

RESET VEHICLE SMART ENTRY SYSTEM BC012R REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA BC011R REMOVE & INSTALL REAR COMPARTMENT LININGS BMI03D

Amount Unit Price Disc %

70 / 110.00

80 / 220.00

120.00

120.00

180 220.00

120.00 /

650.00 X

650.00

650.00

120.00/

450.00 X

650.00

650.00

650.00

1300 5500.00

1500 3200.00

650.00 X 45.50

incld GST

Page

Printed on 9/4/2022 11:01:56 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

AH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

; SQT22000962 : 9. Apr 2022

2 Page

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

: AXA INSURANCE PTE LTD 8 SHENTON WAY

#27-01 AXA TOWER

Customer No. Svc Advisor

Date

: WZA006 ; NG SIN HAI

SINGAPORE 068811 : SMD2876B

Engine No Date | Time

: L15B4534155 : 9. Apr 2022 10:31:59 AM

Registration No Chassis No

: JHMRU1830GX204155 : HRV LX-SIN CVT YM 2016

Surveyor Name

: HAMISH JOSEPH WINSTANLEY

Survey Date Authorisation Date :

Owner's Name Ins Policy No.

| Date of Accident | : 8/4/2022 | | | | | % GST Amount | Amount incld GST |
|----------------------------------|--|------|--------------|----------|----------|-----------------|------------------|
| Item | Description | Qty | Unit Price | Disc % | | 33.60 | 513.60 |
| BOSUN | REMOVE AND RE-INSTALL TAILGATE SPOILER | 1 | 480.00 | 124 | 520.00 | 36.40 | 556.40 |
| BP00R | APPLY BODY UNDERSIDE COATING (N). | 1 | 520.00 Sı | um Labor | 15730.00 | 1,101.10 | 16,831.10 |
| | X AA | 1 | 320.00 | | 320.00 | 22.40 | 342.40 |
| RS-TMP3040L | VPC 4PCS REAR SENSORS · / //// | 1 | 503.90 | 25 | 377.92 | 26.45 | 404.37 |
| 33502-T7A-J01 | LAMP UNITR. X /// LAMP UNITL. X /// | 1 | 503.90 | 25 | 377.92 | 26.45 | 404.37 |
| 33552-T7A-J01 | LIGHT ASSY,R.LID / CM | 1 | 287.80 / | 25 | 215.85 | 15.11 | 230.96 |
| 34150-T7A-J01 | LIGHT ASSYLLID X | 1 | 287.80 | 25 | 215.85 | 15.11 | 230.96 |
| 34155-T7A-J01 68100-T7A-J20ZZ | TAIL CATE COMP. | 1910 | 5812.60 | 25 | 684.45 | 47.91 | 732.36 |
| 74440-T7A-003 | WEATHERSTRIPTAILGATE X | 1 | 105.20 | 25 | 78.90 | 5.52 | 84.42 |
| 74800-T7A-J02 | LOCK ASSYTAILGATE X MA | 1 | 90.10 | 25 | 67.57 | 4.73 | 72.30 |
| 84431-T7A-J01ZA | LINING ASSYTAILGATE X AA | 1 | 145.10 | 25 | 108.82 | 7.62 | 116.44 |
| 75722-T7W-A01 | EMBLEMRR. / //CC | 1 | 15.20 / | 25 | 11.40 | 0.80 | 12.20 |
| 33505-T7A-J01 | REFLECTOR ASSYR.RR. X)) \(\) | 1 | 178.50 | 25 | 133.87 | 9.37 | 143.24 |
| 33555-T7A-J01 | REFLECTOR ASSYL.RR. X nn | 1 | 178.50 | 25 | 133.87 | 9.37 | 143.24 |
| 04717-T7A-000ZZ | FACER.RR.BUMPER CORNER X 110 | 1 | 105.50 | 25 | 79.12 | 5.54 | 84.66 |
| 04718-T7A-000ZZ | FACEL.RR.BUMPER CORNER X MM | 1 | 105.50 | 25 | 79.12 | 5.54 | 84.66 |
| 71593-T7A-000 | SPACER,R.RR.BUMPER SIDE X MM | 1 | 18.00 | 25 | 13.50 | 0.95 | 14.45 |
| 71598-T7A-000 | SPACER,L.RR.BUMPER SIDE X N/ | 1 | 18.00 | 25 | 13.50 | 0.95 | 14.45 |
| 91505-TM8-003 | CLIP,BUMPER / MC | 8 | 2.30 / | 25 | 13.80 | 0.97 | 14.77 |
| 66100-T7A-300ZZ | PANEL COMPRR. 7 X K | 1 | 397.90 | 25 | 298.4 | 2 20.89 | 319.31 |
| 84640-T7A-J01ZA | LINING ASSYRR.PANEL X AA | 1 | 46.80 | 25 | 35.1 | 0 2.46 | 37.56 |
| 04655-T7A-310ZZ | PANEL SET, RR. FLOOR X NA | 1 | 720.30 | 25 | 540.2 | 2 37.82 | 578.04 |
| 72841-SH3-315 | OILSHEET X M | 3 | 43.40 | 25 | 97.6 | 5 6.84 | 104.49 |
| 73214-T7J-H01 | RUBBER CR.WINDSHIELD DAMPER / | 1 | 19.30 | 25 | 14.4 | 7 1.01 | 15.48 |
| 73226-SZW-000 | DAMPERSTD 5X5 AC AC NO. | 1 | 9.10 | 25 | 6.8 | 2 0.48 | 7.30 |
| 73254-T7J-H01 | DUDDED OF WINDSHIELD DAMPER | 00.1 | 19.30 | 25 | 14.4 | 7 1.0 | 15.48 |
| 76711-T6A-003 | CAPPIVOT / AC | 1 | 5.20 | 25 | 3.9 | 0.2 | 7 4.17 |

Printed on 9/4/2022 11:01:56 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

AH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Svc Advisor

Date

Qty

Page

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

8 SHENTON WAY

#27-01 AXA TOWER

: AXA INSURANCE PTE LTD

SINGAPORE 068811

: SMD2876B Registration No

Chassis No Model

: JHMRU1830GX204155

Owner's Name

Ins Policy No.

: 8/4/2022 Date of Accident

: HRV LX-SIN CVT YM 2016 : HAMISH JOSEPH WINSTANLEY

Description

Document No.

: SQT22000962

: 9. Apr 2022

Customer No.

: WZA006

: NG SIN HAI : L15B4534155

Engine No Date | Time

: 9. Apr 2022 10:31:59 AM

Surveyor Name

Survey Date

Authorisation Date :

Unit Price

5.30

| Disc % | Amount | 0% GST Amount | Amount incld GST | | |
|--------|--------|------------------|---------------------|--|--|
| 25 | 15.90 | 1.11 | 17.01 | | |
| 25 | 8.25 | 0.58 | 8.83 | | |
| | | | | | |

FASTENER BW/SHIELD / / 4 91501-S70-003 5.50 2 FASTENER B 91502-\$70-003 6.10 0.40 5.70 3.80 25 2 FASTENER AW/SHIELD // 91536-SS0-J01 128.40 120.00 8.40 60.00 2 WINDSCREEN SEALANT (N) BO-WS-SEALANT 4,372.42 286,06 4086.36 Sum Item

Survey By

Item

Date & Time

Excess

Status

Signature

Total Amount

19,816.36 1,387.16

21,203.52

Total (Inclusive of GST)

21,203.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

Acknowledged by Repairer

Printed on 9/4/2022 11:01:56 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022 255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:

CU0125952 / HAMISH JOSEPH

Chassis No: License No: JHMRU1830GX204155 SMD2876B

Mileage: Engine No: 40697

L15B4534155

Document No:

SVO22018247

Printed By:

SHNG

Order Date:

20. April 2022

Order Time: Service Advisor: 10:38:44 AM

NG SIN HAI

| ITEM | DESCRIPTION | | QTY | UNIT [| DISC % | AMOUNT | 7% GST Am | ount incld |
|----------------------------------|--|-----|---------------------|-----------------------------|--------|---------------------------------|-------------------------------|---------------------------------|
| 04715-T7A-900ZZ 90661-SC7-003 | SUPPLEMENTARY FACE,RR.BUMPER GROMMET SCREW | CRV | 1 2 | 492.50 / 2.50 / SUM P | | 369.37 3.75 373.12 | 25.86 0.26 26.12 | 395.23 4.01 399.24 |
| | | | | TOTA | L SGD | 373.12 | 26.12 | 399.24 |
| | | | Total Pavable (SGD) | | | | | 399.24 |

GST Amount is calculated from individual line(s)