

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003513/UPA3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210009608
Claimant Vehicle No :	JTN7027	Insured Vehicle No :	SLE677D
Date of Loss:	05/03/2022	Nature of Claim:	TP
		Claim No:	6031112778SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JTN7027	Engine No:	G3G5E125806
Make & Model:	YAMAHA 135LC, 134cc ES	Chassis No:	PMYUG0810K0125786
Reg. Date:	24/07/2019 (Man. Year: 2019)	Odometer:	40936 km
Colour:	Red		
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	90/90-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,610.50	2,554.90	2,055.60	44.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	300.00	530.00	63.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,440.50	2,854.90	2,585.60	47.53
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	5,440.50	2,000.00	3,440.50	63.24
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
+ Other Costs (S\$)		35.00		
Nett Liability (S\$)		2,135.00		
Global Sum Settlement (S\$)		2,100.00		

INSPECTION

Date of Assignment:	18/04/2022	Erofia Motor Trading Pte Ltd (HQ)
Date Inspected:	18/04/2022 Inspected At:	1 Kaki Bukit Ave 6 #02-62, Autobay @ Kaki Bukit
		Singapore 417883
		Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Bent / Twisted	640.00 FL	*520.00 FL
2	1		*FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
3	1		*FRONT WHEEL RIM	Not Necessary	380.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*- FL
5	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
6	1		*HANDLE BAR	Bent	88.00 FL	*88.00 FL
7	2		*HANDLE BAR END	Missing / Cut	80.00 FL	*35.00 FL
8	1		*SET HAND GRIP	Not Necessary	55.00 FL	*- FL
9	1		*HANDLE BAR INNER BRACKET	Not Necessary	88.00 FL	*- FL
10	2		*SIDE MIRROR	Broken	110.00 FL	*110.00 FL
11	1		*BRAKE LEVER	Cut	42.00 FL	*30.00 FL
12	1		*HEADLAMP	Cracked	185.00 FL	*185.00 FL
13	1		*SET FRONT SIGNALS	Cracked	140.00 FL	*60.00 FL
14	1		*SET FRONT SIGNAL LOWER GARNISH	Cracked	105.00 FL	*88.00 FL
15	1		*SET FAIRING ASSY	Broken	525.00 FL	*480.00 FL
16	1		*FRONT FOOTREST BRACKET	Bent	65.00 FL	*65.00 FL
17	2		*FRONT FOOTREST RUBBERS	Torn	70.00 FL	*70.00 FL
18	1		*BRAKE PEDAL	Repair	45.00 FL	*- FL
19	1		*REAR FOOTRESTS	O/S Cut	80.00 FL	*40.00 FL
20	2		*REAR FOOTREST BRACKETS	Not Necessary	156.00 FL	*- FL
21	1		*SET REAR SIGNALS	O/S Cut	180.00 FL	*65.00 FL
22	1		*EXHAUST ASSY	Repair	585.00 FL	*- FL
23	1		*EXHAUST PROTECTOR -END	Cut	75.00 FL	*75.00 FL
24	1		*EXHAUST PROTECTOR -BLACK	Cut	55.00 FL	*55.00 FL
25	1		*REAR HANDLE	Cut	228.00 FL	*150.00 FL
26	1		*RADIATOR	Dented	580.00 FL	*400.00 FL
27	1		*BASKET	Chipped	60.00 FL	*60.00 FL
28	1		*SET NUMBER PLATE	Frnt Necessary	38.00 FS	*10.00 FS
29	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
30	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
31	1		*SET STEERING CONE	Necessary	90.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,099.00	2,831.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	488.50	276.10
Total Parts (\$\$)	4,610.50	2,554.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSIG	New	80.00	0.00
2	TO PROVIDE LABOUR	New	400.00	300.00
3	TO REPAIR BODY FRAME	New	350.00	0.00
Gross Labour Cost (\$\$)			830.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >