

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003514/KTY3N2**Date:** 12/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00168952101

Claimant Vehicle No : SJP3023L **Insured Vehicle No :** SMU5552B

Date of Loss: 13/04/2022 Nature of Claim: TP Claim No: SNM22D202566/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP3023L**

Make & Model: HONDA CIVIC, 1.3 IMA CVT (A) Engine No: LDA24019666

Reg. Date: 18/03/2009 (Man. Year: 2008) Chassis No: JHMFD36209S205769

Colour: Metallic Silver Odometer: 278852 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Arivo 8 mm Rear Left Side: Arivo 8 mm

Front Right Side: Arivo 8 mm Rear Right Side: Arivo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,038.40	1,462.32	576.08	28.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	820.00	860.00	51.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,718.40	2,282.32	1,436.08	38.62
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	3,718.40	1,800.00	1,918.40	51.59

INSPECTION

Date of Assignment: 18/04/2022

Date Inspected: 20/04/2022 Inspected At: BLK 1 SIN MING INDUSTRIAL SECTOR C #01-129

Estimated Period of Repair: 4.0 days REPAIRER: NGIAK MOTOR WORKS

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2022)
Parts:	143	HONDA CIVIC 1.3 IMA CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP3023L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER	Repair	539.50 FL	*- FL
2	1		*FRONT LH FENDER INNER SHIELD	Serviceable	149.30 FL	*- FL
3	1		*SET INNER SHIELD CLIPS	Not Necessary	20.00 FL	*- FL
4	1		*FRONT BUMPER	Buckled	659.10 FL	*659.10 FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
6	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	50.70 FL	*50.70 FL
7	1		*FRONT LH HEADLAMP ASSY	Cut	1,089.40 FL	*1,078.10 FL
					Sub Total (S\$)	2,548.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	509.60
					Total Parts (S\$)	2,038.40
						1,462.32

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FOCUS HEADLAMP	New	50.00	20.00
2	COMPUTERISED WHEEL ALIGNMENT	New	150.00	0.00
3	PANEL BEATING	New	680.00	400.00
4	SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (\$\$)			1,680.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >