



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 2593L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	WINDSHIELD	CRACKED	720.00	580.00
1	METER ASSY	NOT NECESSARY	1,050.00	-
1	FRONT COWLING	CUT	680.00	650.00
1	FRONT INNER COWLING	CUT	480.00	300.00
1	FRONT LOWER COVER	CUT	120.00	120.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	288.00	-
1	FRONT FORK ASSY	SERVICEABLE	2,520.00	-
1	HANDLE-BAR	SERVICEABLE	360.00	-
1	HANDLE-BAR BALANCER	CUT	48.00	30.00
1	HAND GRIP	NOT NECESSARY	45.00	-
1	BRAKE LEVER	SCRATCHED	105.00	60.00
1	SET SIDE MIRROR	CUT	312.00	120.00
1	FOOT STEP PANEL	CUT	210.00	210.00
1	FOOT STEP LOWER PANEL	CUT	330.00	185.00
1	SIDE STAND	TO REPAIR SEE LABOUR	128.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	208.00	-
1	REAR SIDE COVER-L/H	CUT	560.00	400.00
1	AIR FILTER BOX COVER	CUT	150.00	150.00
1	DROVE BELT COVER	CUT	300.00	260.00
	LESS 10% DISCOUNT		-861.40	-306.50
			7,752.60	2,758.50
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	NECESSARY	28.00	10.00
2	FORK OIL (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEAT (SN)	NOT NECESSARY	75.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	185.00	-
1	REAR BOX (SN)	CUT	480.00	250.00

Report Ref No. CS/AGI22003516/Uty3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
			978.00	260.00
	LABOUR			
	TO PROVIDE TOWING SERVICE (LOD).	NOT NECESSARY	-	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO SPRAY PAINT.		480.00	200.00
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT FENDER,SIDE STAND AND MAIN STAND.		520.00	300.00
			1,080.00	500.00
GRAND TOTAL			9,810.60	3,518.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/AGI22003516/Uty3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.