



T & C AUTOMOBILE ASSESSORS

ANG BOON CHANG
C/O MING HUA AUTO SERVICES
160 Sin Ming Drive
#02-16 Singapore 575722

REF : TC/2019/475

DATE : 10/9/2018

VEHICLE SURVEY REPORT

REFERENCE

Requested By : Workshop, on behalf of owner
Date of Request : 28/8/2018
Date of Accident : 8/8/2018
Date of Inspection : 28/8/2018
Inspected At : Ming Hua Auto Services
160 Sin Ming Drive
#02-16 Singapore 575722

PARTICULARS OF VEHICLE

Vehicle Registration No	: SJQ46K	Make & Model	: MERCEDES BENZ GLA45 AMG A
Year Make	: 2014	Colour	: SILVER
Engine No	: 1339808 0023648	Chassis No.	: WDC1569522J071986
Engine Capacity	: 1991cc		

CONDITION OF VEHICLE AND TYRES

General Condition	: Good	Mileage	: 116338
Brakes	: Serviceable	Modification	: None
Steering	: Serviceable	Handbrake	: Serviceable

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>
Front RHS	Goodyear	235/45R19	5
Front LHS	Goodyear	235/45R19	5
Rear RHS	Goodyear	235/45R19	6
Rear LHS	Goodyear	235/45R19	6

DESCRIPTION OF DAMAGES

The Vehicle sustained damages at the rear portion.
(For information of damages, please refer to Parts/Labour/Photographs attached)

INSTRUCTION

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.



Annex A

T & C AUTOMOBILE ASSESSORS**ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS**

Vechile No : SJQ46K

Report No : TC/2019/475

S/NO	QTY	DESCRIPTION	CONDITION/ REMARKS	REPAIRER'S ESTIMATES S\$	OUR ASSESSMENT S\$
1	1	Front bumper	Deformed	2,887.60	2,887.60 1,495
2	1	Front bumper lower air grille	Deformed	98.70	98.70
3	1	Front bumper reinforcement	Bent	814.20	814.20 XR
4	1	Front bumper inner foam	Torn/cut	241.50	241.50
5	1 set	Front bumper clips	Necessary	60.00	60.00
6	1	Front grille	Broken/cut	954.70	954.70 824
7	1	Front grille logo	Necessary	85.90	85.90
8	2	Front headlamp @1,187	Broken/cracked	3,877.10	3,877.10 2,374
9	1	Rear bumper	Deformed	2,267.70	2,267.70 1,250
10	1	Rear lower bumper	Deformed	976.60	976.60 525
11	1	Rear lower bumper cover	Necessary	785.90	785.90 XSVC
12	2	Rear bumper side retainer	Broken	146.50	146.50
13	1	Rear bumper centre retainer	Deformed	187.30	187.30
14	1	Rear bumper reinforcement	Bent	752.90	752.90 XHHR
15	1 set	Rear bumper clips	Necessary	60.00	60.00
16	1	Rear tailgate	Buckled	1,897.40	1,897.40 XR
17	1	Rear tailgate emblem logo	Necessary	85.90	85.90
18	1	Rear tailgate "GLA45" emblem	Necessary	65.50	65.50
19	1	Rear tailgate "AMG" emblem	Necessary	65.50	65.50
20	1	Rear tailgate "4MATIC" emblem	Necessary	65.50	65.50
21	1	Rear end panel	Distorted	947.80	947.80 XR
22	1	Rear end panel top garnish	Deformed	337.60	337.60 CRA
23	2	Rear taillamp @676	Broken/cracked	1,845.90	1,845.90 1,352
24	2	Rear exhaust tail chrome pipe RH @385	Deformed	869.40	869.40
				20,377.10	20,377.10
Less : Discount 10%				-2,037.71	-2,037.71
Total :				18,339.39	18,339.39
SPECIAL NETT ITEMS					
25	1 set	Front parking sensor (4 pcs) 2 @185	Malfunction	1,750.00	1,750.00 370
26	1 set	Reverse sensors (4 pcs) @190	Malfunction	1,600.00	1,600.00 380
27	1	Reverse camera	Malfunction	650.00	650.00 XNN
28	1	Front number plate and casing	Dented	80.00	80.00 45
29	1	Rear number plate and casing	Dented	80.00	80.00 XNN
30	1	Rear windscreen sealant	Necessary	130.00	130.00 XNN
				4,290.00	4,290.00
Total Spare Parts :				22,629.39	22,629.39



Annex B

T & C AUTOMOBILE ASSESSORS

LABOUR CHARGES

Vehicle No : SJQ46K

Report No : TC/2019/475

S/NO	DESCRIPTION	REPAIRER'S ESTIMATES S\$	OUR ASSESSMENT S\$	
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	2,900.00	2,600.00	1,000
2	To putty and respray painting on affected areas.	2,500.00	2,200.00	850
3	To check wiring and lightings.	120.00	80.00	60
4	To remove, refix reverse sensor and reverse camera.	220.00	180.00	50
5	To remove, refix tailgate fittings to facilitate repair.	120.00	80.00	X
6	To remove, refix rear upholstery, garnish and attachment.	150.00	120.00	X 60
7	To remove, refix rear windscreen glass.	220.00	180.00	X
8	To apply undersealing.	300.00	250.00	50
Total Labour Charges :		6,530.00	5,690.00	
Total Spare Parts :		22,629.39	22,629.39	
Total Repair Costs :		29,159.39	28,319.39	

Assessor's Recommendation

Repairer Estimate : 29,159.39

Our Adjustment : 28,319.39

Remarks

The repairer has agreed to undertake the repair of S\$28,319.39, with a repair period of working 13 days.

Surveyed By:

THAM KOK SANG

7 days