

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003555/UEA3Q2**Date:** 20/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210066945
Claimant Vehicle No :	FBC4023T	Insured Vehicle No :	SNB5522B
Date of Loss:	06/04/2022	Nature of Claim:	TP
		Claim No:	6686745145SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC4023T	Engine No:	NF01E5007088
Make & Model:	HONDA FJS400, 399cc (A)	Chassis No:	JH2NF01936K000130
Reg. Date:	07/03/2008 (Man. Year: 2006)	Odometer:	251244 km
Colour:	Silver		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/80-14	Rear Tyre Size:	150/70-13
Front Left Side:	ROADTEC 6 mm	Rear Left Side:	ROADTEC 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,942.20	4,128.30	7,813.90	65.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,040.00	380.00	660.00	63.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,982.20	4,508.30	8,473.90	65.27
Approved Total (Overridden) (\$\$)		3,600.00		
Nett Amount (\$\$)	12,982.20	3,600.00	9,382.20	72.27
+ Loss of Use (6.0 x S\$30.00/day) (\$\$)		180.00		
Nett Liability (\$\$)		3,780.00		

INSPECTION

Date of Assignment:	19/04/2022	
Date Inspected:	19/04/2022	Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK ASSY	Serviceable	980.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Serviceable	350.00 FL	*- FL
3	1		*FRONT FENDER	Cracked	480.00 FL	*300.00 FL
4	1		*FRONT RIM	Repair	550.00 FL	*- FL
5	1		*FRONT BRAKE DISC	Not Necessary	420.00 FL	*- FL
6	1		*FRONT RIM SHAFT	Not Necessary	180.00 FL	*- FL
7	1		*FRONT RIM BEARING	Not Necessary	80.00 FL	*- FL
8	1		*FRONT SIDE COVER -R/H	Broken	400.00 FL	*400.00 FL
9	1		*FRONT CENTRE COVER-MATT	Distorted	320.00 FL	*320.00 FL
10	1		*FRONT INNER CENTRE COVER -MATT	Distorted	245.00 FL	*200.00 FL
11	1		*FRONT INNER COVER -BLACK	Cracked	420.00 FL	*420.00 FL
12	1		*WINDSHIELD	Not Necessary	580.00 FL	*- FL
13	1		*HANDLE -BAR	Not Necessary	380.00 FL	*- FL
14	1		*SET HANDLE -BAR END	Not Necessary	150.00 FL	*- FL
15	1		*MIRROR (O/S)	Cut	385.00 FL	*100.00 FL
16	1		*BRAKE LEVER	Not Necessary	215.00 FL	*- FL
17	1		*FRONT SIGNAL (O/S)	Cracked	250.00 FL	*182.00 FL
18	1		*HEADLAMP ASSY	Cracked	950.00 FL	*820.00 FL
19	1		*HEADLAMP BRACKET	Not Necessary	480.00 FL	*- FL
20	1		*FOOTSTEP PANELS	Distorted	580.00 FL	*480.00 FL
21	1		*FOOTSTEP LOWER PANELS	Distorted	450.00 FL	*305.00 FL
22	1		*REAR SIGNALS	Scratched	380.00 FL	*200.00 FL
23	1		*REAR TAIL BOARD	Cut	420.00 FL	*350.00 FL
24	1		*REAR FOOTREST	Serviceable	280.00 FL	*- FL
25	1		*EXHAUST PIPE ASSY	Repair	1,100.00 FL	*- FL
26	1		*EXHAUST PROTECTOR (FRONT)	Cut	245.00 FL	*160.00 FL
27	1		*EXHAUST PROTECTOR (BLACK)	Cut	268.00 FL	*150.00 FL
28	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
29	2		*FORK OILS	Not Necessary	70.00 FS	*- FS
30	2		*FORK OIL SEALS	Not Necessary	180.00 FS	*- FS
31	1		*SET BEARING CONE	Not Necessary	230.00 FS	*- FS
32	1		*SET STICKER	Necessary	380.00 FS	*180.00 FS
33	1		*REAR BOX	Serviceable	480.00 FS	*- FS
34	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,096.00	4,567.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,153.80	438.70
Total Parts (\$\$)	11,942.20	4,128.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD) (NPA)	New	0.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	120.00	0.00
3	TO REPAIR BODY FRAME	New	420.00	0.00
4	TO PROVIDE LABOUR	New	500.00	380.00
Gross Labour Cost (\$\$)			1,040.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >