

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM22003561/Gtce2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	06/05/2022	
	ATTN: CHAN KIAN	CHUAN		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 9740X	Veh. Inspected	ı	FBR 6863T	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03DU6	Excess (\$)		0.00	
	Assign From	CHAN KIAN CHUAN	Assign Date		19/04/2022	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA R15	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	ME1RG6713L0024987	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	100/80-17	MRF		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70 R17	MRF		6 mm	
	L/H Rear Tyre				mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.					
5.	General Information					
	Accident Date	14/07/2021	Inspect Date /	Time	19/04/2022 (05:30 PM)	
	Survey held at	HOTWHEELS SG PTE LTD				
	23 KAKI BUKIT AVENUE 4 #01-11 SYNERGY @ KAKI BUKIT SINGAPORE 417801					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22003561/Gtce2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor