

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III22003564/BTNY3E2

Date: 26/08/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : JTE4504

Insured Vehicle No : SLT2746X

Date of Loss: 14/03/2022

Nature of Claim: TP

Claim No: MFL2022D0001550

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JTE4504**

Make & Model: YAMAHA LAGENDA 115ZR, 115cc

Engine No: E3S7EE068604

Reg. Date: 11/01/2019 (Man. Year: 2018)

Chassis No: PMYUE1510J0073484

Colour: Orange

Odometer: 0 km

Engine Capacity: 114 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17

Rear Tyre Size: 80/90 R17

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,886.49	3,874.54	2,011.95	34.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	600.00	640.00	51.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,126.49	4,474.54	2,651.95	37.21
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	7,126.49	3,550.00	3,576.49	50.19
+ GST 7.00/7.00% (S\$)	498.85	248.50	250.35	50.19
Nett Amount (S\$)	7,625.34	3,798.50	3,826.84	50.19

INSPECTION

Date of Assignment: 19/04/2022

Date Inspected: 19/04/2022 Inspected At:

Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI
BUKIT
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Aug 2022)	
Parts:	N/A	YAMAHA LAGENDA 115ZR 115cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JTE4504)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HANDLE BAR	Bent	175.00 FL	*175.00 FL
2	1		*FRONT HANDLE GRIP	Cut	105.00 FL	*105.00 FL
3	1		*FRONT BRAKE LEVER	Cut	75.00 FL	*75.00 FL
4	1		*FRONT CLUTCH LEVER	Not Necessary	75.00 FL	*- FL
5	1		*FRONT MIRROR ASSY	Cut	95.00 FL	*95.00 FL
6	1		*FRONT COWLING	Cracked	355.00 FL	*355.00 FL
7	1		*FRONT LEFT SIDE COWLING	Distorted	195.00 FL	*195.00 FL
8	1		*FRONT RIGHT SIDE COWLING	Distorted	195.00 FL	*195.00 FL
9	1		*REAR RIGHT PILLION FOOT REST	Not Necessary	65.00 FL	*- FL
10	1		*BALANCER	Cut	65.00 FL	*65.00 FL
11	1		*SET FRONT SIDELAMP	Cracked	295.00 FL	*295.00 FL
12	1		*FRONT HEADLAMP	Cut	385.30 FL	*385.30 FL
13	1		*FRONT HEADLAMP STAY	Not Necessary	136.50 FL	*- FL
14	1		*FRONT HEADLAMP TOP COWLING	Cut	155.30 FL	*155.30 FL
15	2		*FORK STEM	Bent	245.00 FL	*245.00 FL
16	1		*FORK ASSY	Bent	635.00 FL	*635.00 FL
17	1		*FRONT HEADLAMP LOWER COWLING	Deformed	355.00 FL	*355.00 FL
18	1		*SET FRONT SIDE LOWER FAIRING	Deformed	395.00 FL	*395.00 FL
19	1		*FRONT FOOT REST L+R	O/S Bent / N/S NotNecessary	130.00 FL	*65.00 FL
20	1		*FRONT LEFT GEAR SELECTOR	Not Necessary	65.00 FL	*- FL
21	1		*FRONT RIGHT FOOT BRAKE	Not Necessary	65.00 FL	*- FL
22	1		*FRONT RIGHT KICK START PEDAL	Not Necessary	75.00 FL	*- FL
23	1		*FRONT CENTER COWLING	Missing	105.00 FL	*105.00 FL
24	1		*REAR END FENDER	Not Necessary	105.00 FL	*- FL
25	1		*REAR COWLING L+R	O/S Cut / N/S NotNecessary	390.00 FL	*195.00 FL
26	1		*REAR TAIL LAMP	Not Necessary	135.00 FL	*- FL
27	1		*REAR TAIL END GARNISH	Deformed	75.00 FL	*75.00 FL
28	2		*REAR SIGNAL RL	Not Necessary	253.40 FL	*- FL
29	2		*FRONT SIGNAL RL	Not Necessary	244.80 FL	*- FL
30	1		*REAR EXHAUST PIPE	Not Necessary	575.80 FL	*- FL
31	1		*REAR EXHAUST PIPE PROTECTOR	Missing	95.00 FL	*95.00 FL
32	1		*FRONT NUMBER PLATE	Necessary	10.00 FS	*10.00 FS
33	1		*FRONT FORK OIL	Necessary	30.00 FS	*30.00 FS
34	1		*REAR END TAIL BOX ASSY	Not Necessary	150.00 FS	*- FS
35	1		*REAR NUMBER PLATE	Not Necessary	12.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,518.10	4,300.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	631.61	426.06
Total Parts (\$\$)	5,886.49	3,874.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE ACCIDENT AFFECTED AREAS	New	500.00	250.00
2	TO PUTTY AND SPRAY PAINT TO AFFECTED AREAS	New	400.00	200.00
3	TO CHECK ALIGNMENT FORK ASSY	New	300.00	120.00
4	TO FOCUS FRONT LIGHT WIRING	New	40.00	30.00
Gross Labour Cost (\$\$)			1,240.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >