

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM Policy Particulars:- (THIRD PARTY CLAIM)	/Gtce2
SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)	
1. Policy Particulars :- (THIRD PARTY CLAIM)	
Insured Veh. SJY 6295B Veh. Inspected JNY 664	
Policy No. GA469419/1 Coverage (\$) 0.00	
Claim No. S2M03V3G Excess (\$) 0.00	
Assign From ANG YVONNE Assign Date 19/04/2022	
2. Vehicle Particulars & Condition	
Make & Model YAMAHA c.c 0	
Engine No. HIDDEN Year of Reg.	
Chassis No. Colour BLACK	
Odometer 29636 KM Steering IN ORDER	
Brakes IN ORDER Modification NIL	
General GOOD	
3. Conditions of Tyres	
Size Make Balance	
R/H Front Tyre 70/90-17 MAXXIS 4 mm	
L/H Front Tyre mm	
R/H Rear Tyre 80/90-17 MAXXIS 4 mm	
L/H Rear Tyre mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.)
5. General Information	
Accident Date 03/03/2022 Inspect Date / Time 19/04/2022 (05:00	PM)
Survey held at EQBH PTE LTD	
25 KAKI BUKIT ROAD 4 #03-46 SYNERGY @ KB SINGAPORE 417800	
5a. Remarks	
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days	

Report Ref No. CS3/ASM22003565/Gtce2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor