

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003568/AVY3Q2**Date:** 19/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00012982200

**Claimant Vehicle
No :** SMG5249B**Insured Vehicle
No :** GBA7823S

Date of Loss: 30/03/2022

Nature of Claim: TP

Claim
No: SNM22D202602/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMG5249B**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB7100991

Reg. Date: 24/12/2018 (Man. Year: 2018)

Chassis No: GP72000649

Colour: Black

Odometer: 182375 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,789.52	1,545.36	1,244.16	44.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	880.00	450.00	33.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,119.52	2,425.36	1,694.16	41.13
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	4,119.52	1,900.00	2,219.52	53.88
+ GST 7.00/7.00% (S\$)	288.37	133.00	155.37	53.88
Nett Amount (S\$)	4,407.89	2,033.00	2,374.89	53.88

INSPECTION

Date of Assignment: 19/04/2022

Date Inspected: 09/05/2022

Inspected At:

Twincar Automotive Pte Ltd (HQ)
2 KAKI BUKIT AVEUNE 2 #01-17
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Aug 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG5249B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Dented	1,275.40 FL	*1,275.40 FL
2	1		*SET FRONT LH DOOR BLACK TAPE	Necessary	35.80 FL	*35.80 FL
3	1		*FRONT LH DOOR GLASS OUTER MOULDING	Not Necessary	75.60 FL	*- FL
4	1		*FRONT LH DOOR SIDE MIRROR	Damaged	573.20 FL	*573.20 FL
5	1		*FRONT LH DOOR SIDE MIRROR COVER	Cracked	47.30 FL	*47.30 FL
6	1		*FRONT LH FENDER	Repair	1,010.90 FL	*- FL
7	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	93.70 FL	*- FL
8	1		*FRONT LH DOOR INNER INSULATOR MAT	Not Necessary	250.00 FS	*- FS
9	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
					Sub Total (\$\$)	3,411.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	622.38
					Total Parts (\$\$)	2,789.52
						1,931.70
						386.34
						1,545.36

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,TRAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	80.00	60.00
2	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	500.00
3	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	300.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	50.00	20.00
Gross Labour Cost (\$\$)			1,330.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >