



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9889C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER FRONT BUMPER	BENT	521.00	521.00
1	COVER FRONT BUMPER HOLE,LH	DENTED	30.20	30.20
1	ABSORBER,FRONT BUMPER ENERGY	CRACKED	80.20	80.20
1	REINFORCEMENT SUB-ASSY,FRONT BUMPER	TO REPAIR SEE LABOUR	716.60	-
1	MOULDING,FRONT BUMPER SIDE,LH	MTG DISTORTED	95.60	95.60
1	BRACKET,FRONT BUMPER SIDE,LH	DISTORTED	59.30	59.30
1	HOOD SUB-ASSY	TO REPAIR SEE LABOUR	983.10	-
1	HINGE ASSY,HOOD LH	TO REPAIR SEE LABOUR	58.90	-
1	HINGE ASSY,HOOD RH	TO REPAIR SEE LABOUR	58.90	-
1	GRILLE SUB-ASSY,RADIATOR	DISTORTED	422.50	422.50
1	GRILLE,RADIATOR,LOWER NO 1	SERVICEABLE	178.60	-
1	EMBLEM ASSY,RADIATOR GRILLE	NECESSARY	105.80	105.80
1	LINER,FRONT FENDER,LH	SERVICEABLE	210.30	-
1	FENDER SUB-ASSY,FRONT LH	BUCKLED	977.80	977.80
1	FRONT FENDER EMBLEM LH	NECESSARY	54.60	54.60
1	UNIT ASSY,HEADLAMP LH	MTG CRACKED	2,637.60	2,637.60
1	RIM	SERVICEABLE	1,900.10	-
	LESS 25% DISCOUNT		-2,272.78	-1,246.15
			6,818.32	3,738.45
<u>SPECIAL NETT ITEMS</u>				
1	FRT FENDER CLIP (SN)	NOT NECESSARY	65.00	-
1	BONNET INSULATOR CLIP (SN)	NOT NECESSARY	65.00	-
1	FRONT NUMBER PLATE WITH HOLDER (SN)	BENT	200.00	45.00
1	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	75.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	90.00	60.00
			495.00	105.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY,FRONT BUMPER,HOOD SUB-ASSY,HINGE ASSY,HOOD LH AND HINGE ASSY,HOOD RH.		1,600.00	500.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		240.00	30.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	660.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
			4,380.00	1,210.00
	GRAND TOTAL		11,693.32	5,053.45
RECOMMENDED COST OF REPAIRS				5,053.45

Report Ref No. CS/AGI22003572/Kvy3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.