



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623			Ref: CS3/SMO22003574/Kty3e2	
			Date: 06/05/2022	
			Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SDV 2833L	Veh. Inspected	SGS 11K	
Policy No.	D21MTPV01013690	Coverage (\$)	0.00	
Claim No.	CMTD2201141/THE	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	19/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE CAYMAN (A)	c.c	2687	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	WPOZZZ98Z7U752404	Colour	METALLIC SILVER	
Odometer	128072 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55Z R17	MICHELIN	7 mm	
L/H Front Tyre	205/55Z R17	MICHELIN	7 mm	
R/H Rear Tyre	235/50 R17	MICHELIN	4 mm	
L/H Rear Tyre	235/50 R17	MICHELIN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
5. General Information				
Accident Date	02/04/2022	Inspection Date	19/04/2022	
Survey held at	#06-13 SIN MING AUTOCITY			
Repairer	Y2K AUDIO DESIGN			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	