



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

Ref: CS3/ASM22003576/Gvce2

8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811

Date: 06/05/2022

ATTN: ONG KIAN THENG DERICK

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJW 3324G	Veh. Inspected	SGK 8350X
Policy No.	GA606526/1	Coverage (\$)	0.00
Claim No.	S2M03YRR	Excess (\$)	0.00
Assign From	ONG KIAN THENG DERICK	Assign Date	19/04/2022

2. Vehicle Particulars & Condition


Make & Model	TOYOTA LEXUS GS300	c.c	2994
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JTHBG96S505043803	Colour	BLACK
Odometer	235041 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35Z R19	DUNLOP	6 mm
L/H Front Tyre	255/35Z R19	DUNLOP	6 mm
R/H Rear Tyre	255/35Z R19	DUNLOP	6 mm
L/H Rear Tyre	255/35Z R19	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.



5. General Information

Accident Date	18/04/2022	Inspect Date / Time	19/04/2022 (05:30 PM)
Survey held at	3 MOTORWERKZ 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$10,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	------------------------

Report Ref No. CS3/ASM22003576/Gvce2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.