



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 4533S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	XE 4533-REPAIR 22.5KL ALU PETROLEUM RIGID TANK. }		-	-
	TO CARRY OUT GAS-FREE ON TANK BEFORE REPAIR. }		1,200.00	1,200.00
	TO CARRY OUT HYDROSTATIC TEST ON TANK TO ENSURE NO CRACK OR LEAKAGE C/W TEST REPORT. }		2,775.00	2,775.00
	TO CARRY OUT LIQUID PENETRANT TEST ON DENTED BODY SURFACE C/W TEST REPORT. }		1,800.00	1,800.00
	TO PRESS OUT LEFT SIDE ALU BODY DENTED AREA THAT CAUSED BY ACCIDENT. }		4,050.00	4,050.00
	TO CARRY OUT WATER TEST. }		750.00	750.00
	TO REPAIR AND REPLACE ALL OTHER STEEL BRACKET AND MUDGUARD. }		2,250.00	2,250.00
	TO APPLY PUTTY ON THE REPAIR AREA FOLLOW BY SPRAY NEW WHITE PAINT ON THE WHOLE TANKER BODY. }		3,450.00	3,450.00
	TO RE-PASTE SPC TRUCK LOGO DECAL. }		5,100.00	5,100.00
	COST PLUS 20%		4,275.00	-
	COST PLUS 15%		-	3,206.25
			25,650.00	24,581.25
GRAND TOTAL			25,650.00	24,581.25
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				24,581.25

Report Ref No. CS/FCI22003581/Any3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.