



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22003581/Any3m4 Date: 31/01/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 6974U	Veh. Inspected	XE 4533S
Policy No.		Coverage (\$)	0.00
Claim No.	D22001138MFVS	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	19/04/2022
2. Vehicle Particulars & Condition			
Make & Model	MAN TGS 32	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WMA49SZZ3KM802562	Colour	WHITE
Odometer	156242 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	6 mm
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	6 mm
R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	6 mm
L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/04/2022	Inspection Date	21/04/2022
Survey held at	JOO KOON CIRCLE		
Repairer	RYDER AUTO PTE LTD		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	