

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22003592/RPA3Q2**Date:** 14/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SHB1102C **Insured Vehicle No :** SLL7209P

Date of Loss: 17/04/2022 Nature of Claim: TP Claim No: MFL2022D0001998

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB1102C**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS097625

Reg. Date: 12/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FU303572841

Colour: Maroon Odometer: 414710 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 6 mm Rear Left Side: Sailun 6 mm

Front Right Side: Sailun 6 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,817.80	423.67	2,394.13	84.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,794.00	400.00	1,394.00	77.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,611.80	823.67	3,788.13	82.14
Approved Total (Overridden) (S\$)		750.00		
Nett Amount (S\$)	4,611.80	750.00	3,861.80	83.74
+ Loss of Use (2.5 x S\$40.00/day) (S\$)		100.00		
+ Car Rental (2.5 x S\$70.00/day) (S\$)		175.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,032.00		
Global Sum Settlement (S\$)		1,030.00		

INSPECTION

Date of Assignment: 19/04/2022

Date Inspected: 19/04/2022 Inspected At:

Strides Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Sep 2022)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB1102C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PAD ,RR BUMPER ,CTR (DISC 25%) (3 PCS)	Necessary	6.60 F	*4.95 F
2	1		*GUARD ,RR BUMPER LOWER (DISC 25%)	Scratched	558.30 F	*418.72 F
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F
4	2		*PAD ,RR BUMPER ,RH & LH ,1	Not Necessary	3.80 F	*- F
5	2		*PAD ,RR BUMPER ,RH & LH ,2	Not Necessary	3.80 F	*- F
6	2		*PAD ,RR BUMPER ,RH & LH ,3	Not Necessary	3.80 F	*- F
7	2		*SEAL ,RR BUMPER ARM ,RH & LH	Not Necessary	11.00 F	*- F
8	2		*STOPPER RR BUMPER ,RH & LH	Not Necessary	4.30 F	*- F
9	1		*RETAINER ,RR BUMPER RH	Not Necessary	112.70 F	*- F
10	1		*RETAINER ,RR BUMPER LH	Not Necessary	111.50 F	*- F
11	1		*SEAL ,RR BUMPER RH	Not Necessary	85.20 F	*- F
12	1		*SEAL ,RR BUMPER LH	Not Necessary	85.20 F	*- F
13	1		*CLIPS PIECE ,FRT & RR BUMPER	Not Necessary	1.50 F	*- F
14	1		*COVER GUARD RR BUMPER LOWER	Not Necessary	14.80 F	*- F
15	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
16	1		*ANTENNA ELECTRICAL KEY	Not Necessary	60.30 F	*- F
17	1		*COVER ,REAR FLOOR UNDER RH	Not Necessary	169.50 F	*- F
18	1		*COVER ,REAR FLOOR UNDER LH	Not Necessary	234.30 F	*- F
19	1		*COVER REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
20	1		*END PANEL SUB-ASSY ,BODY LOWER BACK	Not Necessary	629.80 F	*- F

F=Franchise part.

Total Parts (S\$) **2,817.80** **423.67**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	738.00	200.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO APPLY RUST -PROOFING ON AFFECTED AREA	New	100.00	0.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
Gross Labour Cost (\$\$)			1,794.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >