

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22003594/KNY3E2

Date: 14/07/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001960792		
Claimant Vehicle No :	SMW2941X	Insured Vehicle No :	SLM7604B		
Date of Loss:	17/04/2022	Nature of Claim:	TP	Claim No:	272914

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW2941X	Engine No:	L15B6024299
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82103714
Reg. Date:	12/11/2020 (Man. Year: 2019)	Odometer:	124307 km
Colour:	Metallic Dark Purple		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,299.72	4,839.96	4,459.76	47.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,055.00	2,220.00	835.00	27.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,354.72	7,059.96	5,294.76	42.86
Approved Total (Overridden) (S\$)		5,650.00		
Nett Amount (S\$)	12,354.72	5,650.00	6,704.72	54.27

INSPECTION

Date of Assignment:	19/04/2022	Trust Autoworks - Ang Mo Kio (HQ)
Date Inspected:	21/04/2022	Inspected At: Blk 5035, #01-345 Ang Mo Kio Industrial Pk 2
Estimated Period of Repair:	9.0 days	Singapore 569538

Adjuster: KENNETH KONG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Jun 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW2941X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	1,350.60 FL	*1,254.80 FL
2	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	105.20 FL	*105.20 FL
3	1		*REAR TAIL-GATE EMBLEM SHUTTLE	Necessary	65.10 FL	*65.10 FL
4	1		*REAR TAIL-GATE OUTER CHROME GARNISH	Serviceable	385.70 FL	*- FL
5	1		*REAR TAIL-GATE INNER LOCK	Dented	305.10 FL	*305.10 FL
6	1		*REAR TAIL-GATE INNER TRIM BOARD	Mtg Cracked	287.40 FL	*287.40 FL
7	1		*REAR TAIL-GATE POCKET	Dented	45.10 FL	*45.10 FL
8	2		*REAR TAIL-GATE REFLECTOR	Serviceable	840.20 FL	*- FL
9	2		*REAR TAIL-LAMP	Serviceable	975.80 FL	*- FL
10	1		*REAR BOOT RUBBER (50%)	Distorted / Dented	195.70 FL	*97.85 FL
11	1		*REAR END PANEL	Bent	685.70 FL	*638.10 FL
12	1		*REAR END PANEL INNER GARNISH	Dented	185.90 FL	*185.90 FL
13	1		*REAR END PANEL LOWER COVER	Serviceable	87.10 FL	*- FL
14	1		*REAR BUMPER	Bent	965.70 FL	*965.70 FL
15	1		*REAR BUMPER CHROME MOULDING	Dented	225.10 FL	*225.10 FL
16	1		*REAR BUMPER TOW COVER	Missing	48.20 FL	*48.20 FL
17	2		*REAR BUMPER SIDE RETAINER	Serviceable	76.40 FL	*- FL
18	2		*REAR BUMPER REFLECTOR	Serviceable	310.40 FL	*- FL
19	1		*REAR BUMPER REFLECTOR SPONGE	O/S Cracked	164.20 FL	*87.10 FL
20	1		*RADIO ANTENNA	Serviceable	125.60 FL	*- FL
21	1		*REAR FENDER INNER TRIM BOARD	O/S Mtg Cracked	970.40 FL	*361.20 FL
22	1		*REAR SPARE TYRE PANEL	Bent	1,072.50 FL	*1,072.50 FL
23	1		*REAR SPARE TOOL CONSOLE BOX	Cracked	205.60 FL	*205.60 FL
24	1		*REAR BOOT TOP COVER BOARD	Serviceable	297.10 FL	*- FL
25	1		*REAR EXHAUST SILENCER	Repair	855.10 FL	*- FL
26	1		*REAR REVERSE SENSOR	Serviceable	200.00 FS	*- FS
27	1		*REAR REVERSE CAMERA	Serviceable	300.00 FS	*- FS
28	1		*REAR TAIL-GATE GLASS SEALANT	Necessary	55.00 FS	*40.00 FS
29	20		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
30	1		*REAR NO PLATE	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,465.90	6,029.95
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,166.18	1,189.99
Total Parts (\$\$)	9,299.72	4,839.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	1,200.00	1,000.00
2	TO PUTTY AND SPRAY PAINT	New	1,200.00	900.00
3	CHECK & RECONNECT WIRING	New	45.00	20.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	120.00	60.00
5	REMOVE / REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	120.00	120.00
6	REMOVE / REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR	New	150.00	60.00
7	REMOVE / REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	100.00	60.00
8	REMOVE / RENEW REAR EXHAUST SILENCER	New	120.00	0.00
Gross Labour Cost (\$\$)			3,055.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >