

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22003595/ETCE2

**Date:** 26/04/2022

### REFERENCE

Insured/Claimant:	CHAN OI LAI	Policy No:	2100374667		
Date of Loss:	13/04/2022	Nature of Claim:	OD	Claim No:	7139384061SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGB3121X		
Make & Model:	AUDI A3 SB, 1.4 TFSI AMBIENTE (A)	Engine No:	CXS068159
Reg. Date:	28/05/2014 (Man. Year: 2014)	Chassis No:	WAUZZZ8VXEA124809
Colour:	White	Odometer:	102332 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$40,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,889.00	23,621.00	21,268.00	47.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	32,864.00	12,154.00	20,710.00	63.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>77,753.00</b>	<b>35,775.00</b>	<b>41,978.00</b>	<b>53.99</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>77,453.00</b>	<b>35,475.00</b>	<b>41,978.00</b>	<b>54.20</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>5,421.71</b>	<b>2,483.25</b>	<b>2,938.46</b>	<b>54.20</b>
<b>Nett Amount (S\$)</b>	<b>82,874.71</b>	<b>37,958.25</b>	<b>44,916.46</b>	<b>54.20</b>

### INSPECTION

Date of Assignment: 19/04/2022

Date Inspected: 19/04/2022 Inspected At:

24 Benoi Sector

Singapore 629857

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 14.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$25,299.00 NETT)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,146.00 FS	*2,146.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT	*Check	175.00 FS	*- FS
4	4		*FRONT BUMPER PULL STRAP-LOWER	*Check	231.00 FS	*- FS
5	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	142.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE GRILLE LH / RH	Broken	244.00 FS	*244.00 FS
7	1		*RADIATOR GRILLE	Broken	765.00 FS	*765.00 FS
8	1		*RADIATOR GRILLE COVER	*Check	109.00 FS	*- FS
9	1		*REINFORCEMENT BEAM	*Check	847.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PC	*Check	93.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	*Check	63.00 FS	*- FS
12	1		*SIGNAGE STICKER CAUTION	Necessary	16.00 FS	*16.00 FS
13	1		*STICKER FOR AIR CON	Necessary	9.00 FS	*9.00 FS
14	1		*SIGNAL HORN - LOW TONE LH	*Check	213.00 FS	*- FS
15	1		*SIGNAL TONE - HIGH TONE RH	*Check	213.00 FS	*- FS
16	1		*BONNET	Dented	3,370.00 FS	*3,370.00 FS
17	1		*BONNET ATTACHMENTS PARTS	Not Necessary	172.00 FS	*- FS
18	2		*BONNET HINGE LH / RH	*Check	136.00 FS	*- FS
19	2		*BONNET HINGE COVER LH / RH	Not Necessary	92.00 FS	*- FS
20	1		*BONNET EDGE PROTECTION	Necessary	31.00 FS	*31.00 FS
21	1		*BONNET CATCH HOOK	*Check	100.00 FS	*- FS
22	2		*BONNET STRIKER LH / RH	*Check	246.00 FS	*- FS
23	1		*BONNET CATCH HOOK	*Check	71.00 FS	*- FS
24	2		*BONNET LID LOCK SWITCH	*Check	455.00 FS	*- FS
25	1		*BONNET BOWDEN CABLE CENTRE	*Check	64.00 FS	*- FS
26	1		*BONNET BOWDEN CABLE COVER	*Check	11.00 FS	*- FS
27	1		*BONNET LID LOCK CABLE	*Check	82.00 FS	*- FS
28	1		*BONNET GAS FILLED STRUT	Not Necessary	110.00 FS	*- FS
29	2		*HEADLIGHT - LH / RH	Broken	5,620.00 FS	*5,620.00 FS
30	2		*HEADLIGHT LIFT CYLINDER - LH / RH	*Check	422.00 FS	*- FS
31	1		*HEADLIGHT LIFT CYLINDER HOSE	*Check	204.00 FS	*- FS
32	1		*LOCK CARRIER	*Check	806.00 FS	*- FS
33	1		*AC CONDENSER	*Check	569.00 FS	*- FS
34	1		*ADDITIONER RADIATOR	*Check	959.00 FS	*- FS
35	1		*RADIATOR	*Check	1,061.00 FS	*- FS
36	2		*RADIATOR BRACKET	*Check	90.00 FS	*- FS
37	2		*RADIATOR BUSH LOWER	*Check	22.00 FS	*- FS
38	6		*COOLANT READY MIXTURE 1.0L	*Check	283.00 FS	*- FS
39	1		*RADIATOR FAN	*Check	1,464.00 FS	*- FS
40	2		*RADIATOR AIR GUIDE LH / RH	*Check	56.00 FS	*- FS
41	1		*RADIATOR SEAL OUTER RH	*Check	9.00 FS	*- FS
42	1		*RADIATOR AIR GUIDE UPPER CENTRE	*Check	14.00 FS	*- FS
43	1		*RADIATOR BRACKET	*Check	21.00 FS	*- FS
44	2		*WHEEL HOUSING LINER LH / RH	Not Necessary	366.00 FS	*- FS
45	1		*MULTI-SWITCH SIDE LIGHTS (BLACK)	Broken	592.00 FS	*592.00 FS
46	1		*REAR BUMPER	Broken	2,201.00 FS	*2,201.00 FS
47	1		*SETS REAR BUMPER FIXING	*Check	201.00 FS	*- FS
48	1		*REAR BUMPER LOCKING MECHANISM LH / RH	N/s Broken	32.00 FS	*16.00 FS
49	1		*REAR BUMPER SPOILER - DOUBLE PIPE	Broken	264.00 FS	*264.00 FS
50	1		*REAR REINFORCEMENT BEAM	*Check	642.00 FS	*- FS
51	2		*REAR BUMPER BRACKET INNER / UPPER RH	Missing	30.00 FS	*30.00 FS
52	2		*REAR BUMPER GUIDE SECTION LH / RH	*Check	150.00 FS	*- FS
53	4		*REAR BUMPER SENSOR INNER / OUTER (NPA)	*Check	0.00 FS	*- FS
54	4		*REAR BUMPER SENSOR SEAL	Necessary	10.00 FS	*10.00 FS
55	1		*SET REAR BUMPER WIRING	*Check	572.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR LID	Dented	3,097.00 FS	*3,097.00 FS
57	1		*REAR LID PACKING ADHESIVE	Necessary	21.00 FS	*21.00 FS
58	1		*REAR LID ATTACHMENTS PARTS	Not Necessary	308.00 FS	*- FS
59	2		*REAR LID HINGE (NPA)	*Check	0.00 FS	*- FS
60	1		*REAR LID SEAL	*Check	229.00 FS	*- FS
61	1		*REAR LID LOCK	*Check	190.00 FS	*- FS
62	1		*REAR LID LOCK COVER	*Check	8.00 FS	*- FS
63	1		*REAR LID PUSH BUTTON	*Check	200.00 FS	*- FS
64	1		*REAR LID LOCK STRIKER	*Check	102.00 FS	*- FS
65	2		*REAR LID CLIPS	Necessary	4.00 FS	*4.00 FS
66	1		*REAR WINDSCREEN	Necessary	905.00 FS	*905.00 FS
67	1		*REAR WINDSCREEN PRIMER	Necessary	22.00 FS	*22.00 FS
68	1		*FOAM STRIPS	Necessary	153.00 FS	*153.00 FS
69	1		*REAR SPOILER FIXING PARTS	Necessary	184.00 FS	*184.00 FS
70	2		*REAR LIGHT REFLECTOR LH / RH	Not Necessary	92.00 FS	*- FS
71	2		*LED TAILLIGHT OUTER LH / RH	*Check	1,948.00 FS	*- FS
72	2		*LED TAILLIGHT INNER LH / RH	Not Necessary	1,948.00 FS	*- FS
73	2		*LED LICENCE PLATE LIGHT	Not Necessary	128.00 FS	*- FS
74	1		*REAR CROSS PANEL	Dented	258.00 FS	*258.00 FS
75	1		*REAR CROSS PANEL REINFORCEMENT BEAM	Dented	1,037.00 FS	*1,037.00 FS
76	2		*REAR CROSS PANEL CONNECTING PLATE LH / RH	Necessary	92.00 FS	*92.00 FS
77	1		*BOOT FLOOR PLATE	*Check	1,982.00 FS	*- FS
78	1		*BOOT FLOOR CROSS MEMBER REAR	*Check	233.00 FS	*- FS
79	1		*REAR CROSS PANEL COVER	*Check	171.00 FS	*- FS
80	1		*REAR LUGGAGE COMPARTMENT FLOOR	*Check	786.00 FS	*- FS
81	1		*REAR CROSS PANEL PLASTIC TRAY	Crushed	319.00 FS	*319.00 FS
82	1		*REAR SILENCER	Dented	776.00 FS	*776.00 FS
83	1		*REAR SILENCER DUAL CLIP	Necessary	65.00 FS	*65.00 FS
84	1		*FRONT SILENCER	*Check	530.00 FS	*- FS
85	1		*FRONT SILENCER DUAL CLIP	*Check	66.00 FS	*- FS
86	1		*EXHAUST SYSTEM RETAINER	Necessary	94.00 FS	*94.00 FS
87	1		*CHROME EXHAUST TAIL PIPE - LH (NPA)	Cut	0.00 FS	*- FS
88	1		*REAR SILENCER HEAT SHIELD	Dented	180.00 FS	*180.00 FS
89	1		*ACYRLIC SEALER	Necessary	180.00 FS	*180.00 FS
90	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
91	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
92	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
93	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
94	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
95	1		*REAR NO PLATE	Cut	60.00 FS	*60.00 FS
96	1		*SUNDRIES	*Check	600.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 44,889.00 23,621.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FRONT HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	New	360.00	0.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE.	New	700.00	500.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDER. TO FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	4,900.00	1,250.00
4	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS.	New	3,500.00	2,200.00
5	TO REMOVE AND TRANSFER REAR PARKING AID.	New	280.00	280.00
6	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	New	480.00	480.00
7	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	New	480.00	480.00
8	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	New	200.00	150.00
9	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	New	400.00	400.00
10	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGES AND RENEW WHERE NECESSARY.	New	1,400.00	1,400.00
11	TO REMOVE AND REINSTALL FUEL TANK TO FACILITATE RENEWAL OF SPARE WHEEL HOUSING. (*Check)	New	600.00	0.00
12	TO REMOVE AND REINSTALL REAR WHEEL SUSPENSION ASSY. (*Check)	New	2,400.00	0.00
13	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER. (*Check)	New	800.00	0.00
14	TO SET UP VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR. (*Check)	New	2,400.00	0.00
15	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING AND SPARE WHEEL HOUSING. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	7,700.00	2,500.00
16	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING.	New	4,000.00	1,650.00
17	TO RENEW REAR AND FRONT EXHAUST SILENCER. TO ALIGN TO POSITION.	New	480.00	480.00
18	TO CARRY OUT PRE/ POST DIAGNOSTIC CHECK.	New	384.00	384.00
19	TO REMOVE AND RENEW AIR CON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE. VACUUM AND REGAS. (* Check)	New	1,400.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>32,864.00</b>	<b>12,154.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >