

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003596/EQCE2**Date:** 25/11/2022**REFERENCE**

Insured/Claimant:	WAYNE ALEXANDER PALMER	Policy No:	1900003623	
Date of Loss:	16/04/2022	Nature of Claim:	OD	Claim No: 0611061513SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2536L	Engine No:	CYR077756
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Chassis No:	WAUZZZ4MXKD009618
Reg. Date:	17/01/2019 (Man. Year: 2018)	Odometer:	36080 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$196,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	46,047.60	23,819.84	22,227.76	48.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	29,892.00	19,742.00	10,150.00	33.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	75,939.60	43,561.84	32,377.76	42.64
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	74,939.60	42,561.84	32,377.76	43.21
+ GST 7.00/7.00% (S\$)	5,245.77	2,979.33	2,266.44	43.21
Nett Amount (S\$)	80,185.37	45,541.17	34,644.20	43.21

INSPECTION

Date of Assignment:	19/04/2022	
Date Inspected:	19/04/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	18.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER -UPPER	Dented	1,451.00 FS	*1,160.80 FS
2	1		*REAR BUMPER	Crushed	1,914.00 FS	*1,531.20 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	217.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Cut	1,407.00 FS	*1,125.60 FS
5	1		*REAR BUMPER SPOILER -LOWER	Not Necessary	119.00 FS	*- FS
6	1		*BOOT LID CONTROL UNIT	Not Necessary	428.00 FS	*- FS
7	1		*TAILGATE SENSOR LINE	Not Necessary	228.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,506.00 FS	*- FS
9	1		*REAR BUMPER HOLDING STRAP	Not Necessary	206.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION -CENTER	Broken	159.00 FS	*126.80 FS
11	2		*REAR BUMPER GUIDE SECTION -LH/RH	Broken	142.00 FS	*56.48 FS
12	3		*REAR PARKING AID SENSOR -INNER /OUTER (NPA)	Not Necessary	0.00 FS	*- FS
13	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
14	1		*REAR LID	Dented	6,480.00 FS	*5,184.00 FS
15	1		*REAR LID ATTACHMENT PARTS	Not Necessary	359.00 FS	*- FS
16	2		*REAR LID HINGE -LH/RH	Not Necessary	342.00 FS	*- FS
17	1		*REAR LID FLAP GASKET	Not Necessary	325.00 FS	*- FS
18	1		*REAR LID LOCK ACTUATOR	Not Necessary	1,478.00 FS	*- FS
19	1		*REAR LID LOCK	Not Necessary	300.00 FS	*- FS
20	1		*REAR LID LOCK FLAP COVER CAP	Not Necessary	13.00 FS	*- FS
21	1		*REAR LID LOCK STRIKER	Not Necessary	96.00 FS	*- FS
22	1		*REAR PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
23	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
24	1		*Q7 EMBLEM	Necessary	104.00 FS	*82.80 FS
25	1		*REAR WINDSCREEN	Necessary	1,307.00 FS	*1,045.60 FS
26	1		*PRIMER	Necessary	22.00 FS	*17.36 FS
27	2		*REAR SPOILER -LH/RH	Necessary	514.00 FS	*410.40 FS
28	1		*REAR SPOILER FOAM STRIPS	Necessary	153.00 FS	*122.00 FS
29	1		*REAR SPOILER FIXING PARTS	Necessary	69.00 FS	*54.96 FS
30	1		*REAR BUMPER TAIL LIGHT -LH/RH	N/S Cut	804.00 FS	*321.60 FS
31	2		*LICENCE PLATE LIGHT -LH/RH	Not Necessary	209.00 FS	*- FS
32	1		*TAIL LIGHT -LH/RH	N/S Broken	4,558.00 FS	*1,823.20 FS
33	1		*REAR FENDER LH	Dented	7,776.00 FS	*6,220.80 FS
34	1		*QUARTER WINDOW -LH	Necessary	1,053.00 FS	*842.40 FS
35	1		*RPIMER	Necessary	22.00 FS	*17.36 FS
36	1		*REAR END PANEL	Not Necessary	668.00 FS	*- FS
37	1		*REAR END PANEL REINFORCEMENT	Not Necessary	1,506.00 FS	*- FS
38	1		*REAR END PANEL TRIM	Not Necessary	475.00 FS	*- FS
39	2		*REAR WHEEL ARCH COVER -LH/RH	Necessary	414.00 FS	*330.40 FS
40	1		*EXHAUST TAIL PIPE TRIM -LH/RH	N/S Cut	712.00 FS	*284.80 FS
41	1		*REAR SILENCER CENTER	Not Necessary	2,880.00 FS	*- FS
42	1		*DUAL CLIP	Not Necessary	68.00 FS	*- FS
43	2		*EXHAUST SILENCER BRACKET -LH/RH	Not Necessary	90.00 FS	*- FS
44	1		*WIPER ARM	Not Necessary	107.00 FS	*- FS
45	1		*WIPER BLADE	Cut	32.00 FS	*25.28 FS
46	1		*WIPER CAP	Not Necessary	20.00 FS	*- FS
47	1		*WATER JET	Not Necessary	36.00 FS	*- FS
48	1		*REAR SILL PANEL TRIM STRIP -LH OUTER	Necessary	182.00 FS	*145.60 FS
49	1		*REAR WHEEL SPOILER -LH	Not Necessary	40.00 FS	*- FS
50	1		*REAR WHEEL HOUSING LINER -LH	Broken	347.00 FS	*277.60 FS
51	1		*REAR SILENCER HEAT SHIELD	Not Necessary	171.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*STATIC MIXER	Necessary	27.60 FS	*27.60 FS
53	1		*2 PACK SPOXY ADHESIVE	Necessary	122.00 FS	*49.12 FS
54	1		*ALUMINIUM POWDER	Necessary	637.00 FS	*509.60 FS
55	1		*HARDENER	Necessary	232.00 FS	*185.60 FS
56	1		*ALUMINIUM PRIMER	Necessary	233.00 FS	*186.40 FS
57	1		*CLEANING BLOCK	Not Necessary	96.00 FS	*- FS
58	1		*ARYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
59	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
60	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
61	1		*ALUMINIUM FILLER POWDER	Not Necessary	280.00 FS	-
62	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
63	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
64	1		*EAR NO PLATE	Not Necessary	60.00 FS	*- FS
65	1		*SUNDRIES	Necessary	500.00 FS	*50.88 FS
66	1		*SEAL FOR SILL PANEL - LH (Supplementary)	Bent	282.00 FS	*225.20 FS
67	1		*REAR FENDER VENT TRIM - LH (Supplementary)	Broken	80.00 FS	*63.92 FS
68	1		*REAR FENDER CONNECTING PLATE (Supplementary)	Bent	109.00 FS	*86.96 FS
69	1		*COUNTERSUNK RIVET (4X8) (Supplementary)	Necessary	115.00 FS	*92.00 FS
70	1		*COUNTERSUNK RIVET (4X12) (Supplementary)	Necessary	225.00 FS	*180.00 FS
71	1		*POP RIVET (Supplementary)	Necessary	30.00 FS	*24.00 FS
72	1		*2-PACK EPOXY ADHESIVE (Supplementary)	Not Necessary	122.00 FS	*- FS
73	1		*2 PK FILL FOAM (Supplementary)	Not Necessary	154.00 FS	*- FS
74	2		*SOUND ABSORBER (Supplementary)	Not Necessary	259.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	46,047.60	23,819.84
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM ,WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY	New	480.00	480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	480.00
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	New	200.00	150.00
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	400.00
6	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	300.00	300.00
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT .INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	Repair	1,800.00	1,800.00
8	TO REMOVE AND REINSTALL REAR SEAT ,BACK REST ,HAT TRAY ,ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,800.00	1,800.00
9	TO SETUP AND PLACE THE VEHICLE IN ALUMINIUM BAY	New	1,800.00	1,800.00
10	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID TO CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLING TO REPAIR RHS REAR FENDER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	10,000.00	6,000.00
11	TO RESPRAY REAR BUMPER REAR LID ,HINGES ,LHS REAR FENDER ,LHS SILL PANEL ,DOOR ENTRANCE DRAIN CHANNEL ROOF CHANNEL REAR END PANELLING AND RHS REAR FENDER	New	8,000.00	3,900.00
12	TO CARRY OUT ALUMINIUM PRIMER WORKS	New	900.00	900.00
13	TO RENEW BOTH REAR EXHAUST SILENCER WITH CENTER EXHAUST SILENCER ,TO ALIGN TO POSTION	New	480.00	280.00
14	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
15	TO CUT OUT AND WELD LHS REAR FENDER CONNECTING PLATE (Supplementary)	New	1,800.00	600.00
16	TO RESPRAY LHS REAR FENDER CONNECTING PLATE (Supplementary)	New	900.00	300.00
Gross Labour Cost (\$\$)			29,892.00	19,742.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >