



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 7129U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	519.31	519.31
1	REAR BUMPER BRACKET	NOT NECESSARY	191.90	-
1	REAR BUMPER REINFORCEMENT	BENT	628.93	382.00
1	REAR BUMPER CENTER GUARD	DEFORMED	650.63	428.71
1	REAR BUMPER PAD	NOT NECESSARY	414.81	-
1	TAIL GATE	BENT	1,339.20	1,112.50
1	TAIL GATE LOCK ASSY	NOT NECESSARY	629.04	-
	LESS 20% DISCOUNT		-874.78	-
	LESS 25% DISCOUNT		-	-610.63
			3,499.04	1,831.89
	<u>SPECIAL NETT ITEMS</u>			
15	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR NUMBER PLATE CASING (SN)	SCRATCHED	20.00	10.00
			70.00	40.00
	<u>LABOUR</u>			
	TO REMOVE AND RENEW REAR DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS.		1,000.00	450.00
	TO RESPRAY AFFECTED AREAS.		800.00	400.00
	TO REMOVE / REFIX WIRING CHECKS.		60.00	40.00
	TO TUFF COAT AFFECTED AREA.		60.00	30.00
			1,920.00	920.00
	GRAND TOTAL		5,489.04	2,791.89
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,250.00

Report Ref No. CS/INC22003598/Rvy3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.