

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT | | | | | | |
|------------------------------------|--|---------------------------------|----------------|---------|-------------------------|--|
| | NTUC INCOME IN: | SURANCE CO-OPERATIVE LTD | | Ref: | CS/INC22003599/Uqy3s2 | |
| | 73 BRAS BASAH F #05-01 NTUC TRA 189556 | ROAD DE UNION HOUSESINGAPORE | | Date: | 20/05/2022 | |
| | ATTN: LIM SEREN | E | | Code: | INC | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLJ 4530R | Veh. Inspected | | SJP 5317B | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | MT/1169021-002 | Excess (\$) | | 0.00 | |
| | Assign From | ANNIE KOH | Assign Date | | 19/04/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | SUZUKI SWIFT (A) | c.c | | 1586 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2009 | |
| | Chassis No. | JSAEZC31S00203898 | Colour | | WHITE | |
| | Odometer | 240133 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/45Z R17 | KUMHO | | 6 mm | |
| | L/H Front Tyre | 205/45Z R17 | KUMHO | | 6 mm | |
| | R/H Rear Tyre | 205/45Z R17 | KUMHO | | 6 mm | |
| | L/H Rear Tyre | 205/45Z R17 | KUMHO | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| _ | | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 17/04/2022 | Inspect Date / | ııme | 19/04/2022 (03:15 PM) | |
| | Survey held at | • | | | | |
| r - | - September - Sept | | | | | |
| 5a. | Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. | | | | | |
| | B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | MAL PERIOD FOR REPAIR: | | 4 Worki | ing Days | |