

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003631/VNCE2

Date: 22/07/2022

REFERENCE

Insured/Claimant:	TAN SIAN LIP	Policy No:	1800011575		
Date of Loss:	09/04/2022	Nature of Claim:	OD	Claim No:	5276082845SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW3784M		
Make & Model:	AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A)	Engine No:	CHZ642950
Reg. Date:	08/02/2018 (Man. Year: 2017)	Chassis No:	WAUZZZ8V0J1044087
Colour:	Blue	Odometer:	72099 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$83,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,404.00	6,962.80	8,441.20	54.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,402.00	2,042.00	4,360.00	68.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,806.00	9,004.80	12,801.20	58.70
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	21,506.00	8,704.80	12,801.20	59.52
+ GST 7.00/7.00% (S\$)	1,505.42	609.34	896.08	59.52
Nett Amount (S\$)	23,011.42	9,314.14	13,697.28	59.52

INSPECTION

Date of Assignment:	20/04/2022		
Date Inspected:	14/04/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: Thevan Thomas Karthikesavan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	2,433.00 FS	*1,946.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-LH	Serviceable	43.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	179.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Not Necessary	571.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT -LH	Serviceable	318.00 FS	*- FS
7	1		*FRONT BUMPER TRIM COVER -LH	Scratched	182.00 FS	*145.20 FS
8	1		*FRONT BUMPER ADAPTER -LH	Serviceable	42.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	1,578.00 FS	*- FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Serviceable	210.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Scratched	210.00 FS	*168.00 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Serviceable	211.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Serviceable	136.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Serviceable	847.00 FS	*- FS
15	1		*AIR COND STICKER	Serviceable	9.00 FS	*- FS
16	1		*CAUTION STICKER	Serviceable	16.00 FS	*- FS
17	1		*HORN -LH	Serviceable	213.00 FS	*- FS
18	1		*FRONT FENDER -LH	Repair	954.00 FS	*- FS
19	5		*FRONT FENDER POP RIVET	Serviceable	19.00 FS	*- FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Serviceable	75.00 FS	*- FS
21	1		*FRONT FENDER BRACKET -LH	Serviceable	46.00 FS	*- FS
22	1		*FRONT FENDER BRACE	Serviceable	107.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER -LH	Serviceable	183.00 FS	*- FS
24	1		*HEADLIGHT -LH	Scratched	5,879.00 FS	*4,703.20 FS
25	1		*LIFT CYLINDER -LH	Serviceable	156.00 FS	*- FS
26	1		*LIFT CYLINDER HOSE-LH	Serviceable	78.00 FS	*- FS
27	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Serviceable	21.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE -LH	Serviceable	28.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE -UPPER CENTER	Serviceable	14.00 FS	*- FS
30	1		*BONNET CATCH HOOK	Serviceable	71.00 FS	*- FS
31	1		*FRONT NO PLATE	Serviceable	80.00 FS	*- FS
32	1		*SUNDRIES	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,404.00 6,962.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT.TO REPAIR BONNET .RE- ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,500.00	500.00
4	TO RESPRAY FRONT BUMPER ,BONNET AND LHS FRONT FENDER	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,402.00	2,042.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >