



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8326R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT	1,052.20	1,052.20
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE BRACKET RH	CUT	22.40	22.40
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	663.00	-
1	FRONT FENDER SHIELD RH	NOT NECESSARY	174.90	-
1	FRONT FENDER RETAINER RH	NOT NECESSARY	217.20	-
1	HEADLAMP RH	CRACKED	1,388.00	1,388.00
	LESS 20% DISCOUNT		-707.94	-496.92
			2,831.76	1,987.68
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		800.00	420.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK LIGHTINGS.		40.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
			1,500.00	950.00
GRAND TOTAL			4,331.76	2,937.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,350.00

Report Ref No. NS/INC22003635/Gqcn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.