



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9877C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER COVER	TO REPAIR SEE LABOUR	481.10	-
10	FRT BUMPER CLIPS	NOT NECESSARY	22.00	-
1	FRT BUMPER SIDE BRACKET RH	NOT NECESSARY	28.00	-
1	FRT FENDER RH	BUCKLED	588.80	588.80
1	FRT FENDER SHIELD RH	NOT NECESSARY	164.70	-
1	EMBLEM-BLUE DRIVE RH	NECESSARY	26.60	26.60
1	FRT WHEEL HUB CAP RH	SCRATCHED	346.40	346.40
	LESS 20% DISCOUNT		-331.52	-192.36
			1,326.08	769.44
	<u>SPECIAL NETT ITEMS</u>			
1	FRT DOOR COMFORT LOGO RH (SN)	NECESSARY	75.00	75.00
			75.00	75.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT BUMPER COVER.		800.00	350.00
	SPRAY PAINTING CHARGE.		800.00	500.00
	TUFF KOTE.		60.00	40.00
			1,660.00	890.00
	GRAND TOTAL		3,061.08	1,734.44
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,400.00

Report Ref No. NS/INC22003639/Gqcn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.