

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB22003644/UPA3Q2**Date:** 20/03/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SKJ9290L **Insured Vehicle No :** SMS2545C

Date of Loss: 14/04/2022 Nature of Claim: TP Claim No: MFL2022D0001974

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ9290L**
 Make & Model: MERCEDES-BENZ A200, 1.3 AMG LINE (A) Engine No: 28291480020153
 Reg. Date: 14/01/2019 (Man. Year: 2018) Chassis No: WDD1770872J026282
 Colour: Silver Odometer: 34950 km
 Engine Capacity: 1333 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm
 Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,889.90	3,870.94	17,018.96	81.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	1,690.00	2,350.00	58.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,929.90	5,560.94	19,368.96	77.69
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	24,929.90	5,000.00	19,929.90	79.94
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,307.45		
Global Sum Settlement (S\$)		5,300.00		

INSPECTION

Date of Assignment: 20/04/2022

Date Inspected: 20/04/2022 Inspected At:

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
 Bukit
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2022)
Parts:	144	MERCEDES-BENZ A200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ9290L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	2,980.70 F	*- FL
2	1		*BOOTLID REAR LOGO	Not Necessary	158.00 F	*- FL
3	1		*BOOTLID A 200 EMBLEM	Not Necessary	142.00 F	*- FL
4	2		*BOOTLID REFLECTORS	Not Necessary	1,380.00 F	*- FL
5	1		*BOOTLID INNER TRIM	Not Necessary	331.00 F	*- FL
6	1		*BOOTLID INNER LOCK	Not Necessary	366.80 F	*- FL
7	1		*BOOTLID WEATHERSTRIP	Not Necessary	385.50 F	*- FL
8	1		*REAR BUMPER	Dented	2,245.20 F	*1,815.32 FL
9	1		*SET REAR BUMPER BEAM	Bent	844.50 F	*522.15 FL
10	1		*REAR BUMPER SIDE RETAINERS	O/S Twisted	190.00 F	*95.00 FL
11	1		*REAR BUMPER LOWER SKIRTING	Distorted	850.00 F	*681.25 FL
12	1		*REAR BUMPER LOWER CHROME O/S	Scratched	355.00 F	*190.00 FL
13	1		*REAR BUMPER REFLECTORS	O/S Cracked / N/S NotNecessary	170.00 F	*48.00 FL
14	1		*REAR BUMPER PDC SENSORS (4PCS)	O/S Damaged(1Pc Only)	900.00 F	*195.00 FL
15	1		*REAR BUMPER INNER TOP RETAINER	Twisted	231.00 F	*228.32 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	80.00 F	*60.00 FL
17	1		*REAR BUMPER LOWER SIDE COVERS	O/S Twisted / N/S NotNecessary	210.00 F	*92.00 FL
18	1		*REAR END PANEL	Repair	1,215.00 F	*- FL
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	486.90 F	*- FL
20	1		*REAR FENDER FLOOR PANEL	Not Necessary	955.10 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	627.20 F	*- FL
22	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	568.00 F	*- FL
23	2		*TAILLAMPS	Not Necessary	1,960.00 F	*- FL
24	1		*TAILLAMP LOWER BRACKETS	O/S Cracked	216.00 F	*108.00 FL
25	1		*REAR EXHAUST	Not Necessary	2,666.00 F	*- FL
26	1		*REAR EXHAUST HEAT SHIELD	Bent	276.00 F	*266.00 FL
27	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
28	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,889.90	4,301.04
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	430.10
Total Parts (\$\$)	20,889.90	3,870.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	100.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	80.00	0.00
6	TO RESET & DIAGNOSIS REPROGRAMME SYSTEM	New	380.00	100.00
7	TO SPRAY RUST PROOFING	New	150.00	20.00
8	TO DISMANTLE & REFIX FUEL TANK	New	80.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	600.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	800.00
Gross Labour Cost (S\$)			4,040.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >