

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003656/KVY3M4**Date:** 31/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00049812204

**Claimant Vehicle No :** SND6019X **Insured Vehicle No :** SJD4591U

Date of Loss: 17/04/2022 Nature of Claim: TP Claim No: SNM22D202617/C2/BILLY

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SND6019X**

Make & Model: TESLA MODEL 3, 2.0 E (A) Engine No: 0

Reg. Date: 12/01/2022 (Man. Year: 2021) Chassis No: LRW3F7FA6MC416169

Colour: Metallic Red Odometer: 2550 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/45ZR18 Rear Tyre Size: 235/45ZR18

Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm

Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,782.50	2,287.92	1,494.58	39.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,600.00	1,070.00	40.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,452.50</b>	<b>3,887.92</b>	<b>2,564.58</b>	<b>39.75</b>
<b>+ GST 7.00/7.00% (S\$)</b>	451.68	272.15	179.53	39.75
<b>Nett Amount (S\$)</b>	<b>6,904.18</b>	<b>4,160.07</b>	<b>2,744.11</b>	<b>39.75</b>

**INSPECTION**

Date of Assignment: 19/04/2022

Date Inspected: 20/04/2022 Inspected At: 10 ANG MO KIO INDUSTRIAL PARK 2A  
#01-05 AMK AUTOPOINT SINGAPORE 568047  
REPAIRER : OPTIMA WERKZ PTE LTD

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2022)
<b>Parts:</b>	143	TESLA MODEL 3 2.0 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SND6019X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Repair	953.27 FL	*- FL
2	1		*REAR DOOR WEATHERSTRIP RH	Serviceable	88.79 FL	*- FL
3	1		*REAR FENDER RH	Bent	1,345.77 FL	*1,345.77 FL
4	1		*REAR FENDER QUARTER GLASS RH WITH MOULDING	Necessary	280.37 FL	*280.37 FL
5	1		*REAR RIM RH (DENTED)	Not Consistent With The Impact	467.29 FL	*- FL
6	1		*REAR RIM COVER RH	Repair	32.71 FL	*- FL
7	1		*REAR BUMPER	Dented / Cut	663.55 FL	*663.55 FL
8	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	7.48 FL	*- FL
9	1		*REAR BUMPER REVERSE SENSOR	Shorted	158.88 FL	*158.88 FL
10	1		*REAR BUMPER REVERSE SENSOR BRACKET	Necessary	4.67 FL	*4.67 FL
11	1		*REAR QUARTER GLASS SEALANT RH	Necessary	80.00 FS	*30.00 FS
12	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
13	1		*REAR DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,182.78</b>	<b>2,533.24</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	400.28	245.32
<b>Total Parts (\$\$)</b>	<b>3,782.50</b>	<b>2,287.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.	New	800.00	600.00
2	FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH, REAR BUMPER & ETC.	New	800.00	660.00
3	TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.	New	150.00	0.00
4	TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.	New	300.00	100.00
5	TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	New	120.00	50.00
6	TO REMOVE & REFIX REAR QUARTER GLASS RH & ETC.	New	150.00	60.00
7	TO WHEEL ALIGNMENT & BALANCING.	New	80.00	20.00
8	TO DIAGNOSIS FAULT CODE & RESET MEMORY.	New	150.00	90.00
9	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	New	120.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>2,670.00</b>	<b>1,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >