



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4709E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	BENT	798.50	798.50
1	REAR BOOT LOCK	BENT	185.15	185.15
1	REAR BOOT RUBBER	CUT	211.50	211.50
1	REAR BOOT "AXIO" EMBLEM	NECESSARY	68.50	68.50
1	REAR BOOT "COROLLA" EMBLEM	NECESSARY	62.60	62.60
1	REAR BOOT "HYBRID" EMBLEM	NECESSARY	78.00	78.00
1	REAR BOOT OUTER MOULDING	NOT NECESSARY	240.00	-
1	REAR LEFT TAILLAMP	CRACKED	481.30	481.30
1	REAR LEFT TAILLAMP LOWER BRACKET	BROKEN	95.00	95.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	608.80	-
1	REAR END PANEL INNER GARNISH	DEFORMED	195.00	195.00
1	REAR BUMPER	DEFORMED	1,014.30	1,014.30
1	REAR BUMPER TOP BRACKETS LH	NOT NECESSARY	87.90	-
1	REAR BUMPER REFLECTORS LH	BROKEN	82.00	82.00
1	REAR BUMPER SIDE RETAINERS LH	CUT	71.90	71.90
1	REAR FENDER LH	TO REPAIR SEE LABOUR	987.50	-
1	REAR FENDER INNER COWLING LH	NOT NECESSARY	125.00	-
1	REAR FENDER INNER TRIM	NOT NECESSARY	475.00	-
	LESS 25% DISCOUNT		-1,466.99	-835.94
			4,400.96	2,507.81
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-
			430.00	30.00
<u>LABOUR</u>				
	TO PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR FENDER LH.		800.00	400.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	40.00

Report Ref No. CS/AIS22003662/Gvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND RESPRAY ON ACCIDENT PORTION.	NOT NECESSARY	800.00	600.00
	TO CHECK WIRING.		80.00	30.00
	TO APPLY ANTI-RUST CORROSION ON AFFECTED AREAS.		60.00	-
			1,820.00	1,070.00
GRAND TOTAL			6,650.96	3,607.81
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/AIS22003662/Gvy3m4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.