

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003663/ANY3Q2**Date:** 09/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00002702201

**Claimant Vehicle  
No :** SLA7744T**Insured Vehicle  
No :** GW4698G

Date of Loss: 18/04/2022

Nature of Claim: TP

Claim  
No: SNM22D202612/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLA7744T**

Make &amp; Model: HYUNDAI TUCSON, 2.0 (A)

Engine No: HIDDEN

Reg. Date: 01/03/2016 (Man. Year: 2016)

Chassis No: KMHJ3813MGU184975

Colour: Blue

Odometer: 91525 km

Engine Capacity: 1999 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 14,118.49         | 8,438.48          | 5,680.01          | 40.23         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,310.00          | 1,540.00          | 1,770.00          | 53.47         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>17,428.49</b>  | <b>9,978.48</b>   | <b>7,450.01</b>   | <b>42.75</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>7,900.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>17,428.49</b>  | <b>7,900.00</b>   | <b>9,528.49</b>   | <b>54.67</b>  |

**INSPECTION**

Date of Assignment: 22/08/2022

Date Inspected: 20/04/2022

Inspected At: Unimotor Co (HQ)  
NO 1 KAKI BUKIT AVE 6 #01-94  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 09 Dec 2022)            |
| <b>Parts:</b>        | 143  | HYUNDAI TUCSON 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                        |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLA7744T)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1   | 1   |          | *REAR TAILGATE ASSY                       | Dented        | 1,938.00 FL | *1,758.00 FL |
| 2   | 1   |          | *REAR TAILGATE LAMP (R)                   | Cracked       | 686.20 FL   | *686.20 FL   |
| 3   | 1   |          | *REAR TAILGATE INNER LOCK                 | Damaged       | 667.00 FL   | *395.00 FL   |
| 4   | 1   |          | *REAR TAILGATE STRIKER                    | Not Necessary | 38.70 FL    | *- FL        |
| 5   | 2   |          | *REAR TAILGATE HINGES                     | Not Necessary | 196.80 FL   | *- FL        |
| 6   | 1   |          | *REAR TAILGATE WEATHERSTRIP               | Cut           | 159.80 FL   | *159.80 FL   |
| 7   | 1   |          | *REAR TAILGATE HYUNDAI EMBLEM ASSY        | Necessary     | 48.30 FL    | *48.30 FL    |
| 8   | 1   |          | *REAR TAILGATE HYUNDAI TUCSON EMBLEM      | Necessary     | 88.40 FL    | *88.40 FL    |
| 9   | 2   |          | *REAR TAILGATE NUMBER PLATE LAMP          | Not Necessary | 90.40 FL    | *- FL        |
| 10  | 1   |          | *REAR TAILGATE OUTER GARNISH              | Deformed      | 618.40 FL   | *618.40 FL   |
| 11  | 1   |          | *REAR TAILGATE OUTER GARNISH BRACKET      | Cracked       | 145.70 FL   | *145.70 FL   |
| 12  | 1   |          | *REAR TAILGATE INNER TRIM BOARD           | Cracked       | 338.80 FL   | *338.80 FL   |
| 13  | 1   |          | *REAR TAILGATE STAY ABSORBER              | Not Necessary | 599.20 FL   | *- FL        |
| 14  | 1   |          | *REAR TAILGATE INNER HANDLE GARNISH       | Not Necessary | 42.60 FL    | *- FL        |
| 15  | 1   |          | *REAR TAILGATE GLASS ASSY                 | Shattered     | 1,644.80 FL | *1,358.00 FL |
| 16  | 1   |          | *REAR TAILGATE WIPER MOTOR ASSY           | Damaged       | 889.60 FL   | *585.00 FL   |
| 17  | 1   |          | *REAR TAILGATE WIPER ARM                  | Not Necessary | 222.40 FL   | *- FL        |
| 18  | 1   |          | *REAR TAILGATE WIPER BLADE                | Not Necessary | 84.60 FL    | *- FL        |
| 19  | 1   |          | *REAR TAILGATE GLASS MOULDING             | Necessary     | 105.60 FL   | *105.60 FL   |
| 20  | 1   |          | *REAR TAILLAMP ASSY (R)                   | Cracked       | 886.60 FL   | *886.60 FL   |
| 21  | 1   |          | *REAR BUMPER FACE (TOP)                   | Deformed      | 755.80 FL   | *755.80 FL   |
| 22  | 1   |          | *REAR BUMPER FACE (LOWER)                 | Deformed      | 543.20 FL   | *543.20 FL   |
| 23  | 1   |          | *REAR BUMPER REINFORCEMENT                | Cracked       | 432.80 FL   | *271.00 FL   |
| 24  | 1   |          | *REAR BUMPER INNER SPONGE                 | Not Necessary | 286.50 FL   | *- FL        |
| 25  | 2   |          | *REAR BUMPER SIDE RETAINER                | Not Necessary | 68.00 FL    | *- FL        |
| 26  | 1   |          | *REAR BUMPER TOWING COVER GARNISH         | Damaged       | 25.80 FL    | *25.80 FL    |
| 27  | 1   |          | *REAR R/H BUMPER REFLECTOR LAMP           | Cracked       | 102.70 FL   | *102.70 FL   |
| 28  | 8   |          | *REAR BUMPER CLIPS                        | Necessary     | 48.00 FL    | *30.00 FL    |
| 29  | 1   |          | *REAR EXHAUST BOX                         | Not Necessary | 914.80 FL   | *- FL        |
| 30  | 1   |          | *TAIL END PANEL                           | Repair        | 785.80 FL   | *- FL        |
| 31  | 1   |          | *PANEL LINING                             | Deformed      | 120.80 FL   | *120.80 FL   |
| 32  | 1   |          | *REAR NUMBER PLATE                        | Not Necessary | 50.00 FS    | *- FS        |
| 33  | 1   |          | *SET REAR CCTV CAMERA                     | Not Necessary | 420.00 FS   | *- FS        |
| 34  | 1   |          | *REAR TAILGATE OUTER GARNISH CHROME STRIP | Cut           | 180.00 FS   | *150.00 FS   |
| 35  | 1   |          | *REAR BUMPER TOP CHROME STRIP GARNISH     | Necessary     | 220.00 FS   | *180.00 FS   |
| 36  | 1   |          | *REAR BUMPER LOWER SPOLER                 | Cracked       | 550.00 FS   | *550.00 FS   |
| 37  | 1   |          | *REAR BUMPER REVERSE SENSOR               | Damaged       | 280.00 FS   | *200.00 FS   |
| 38  | 1   |          | *REAR WINDSCREEN RUBBER SEALANT           | Necessary     | 80.00 FS    | *60.00 FS    |
| 39  | 1   |          | *REAR EXHAUST CHROME PIPE                 | Bent          | 120.00 FS   | *80.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                  |                  |
|--|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>15,476.10</b> | <b>10,243.10</b> |
| <b>- List Item Discount on L Items 10.00/20.00% (\$\$)</b> | 1,357.61         | 1,804.62         |
| <b>Total Parts (\$\$)</b>                                  | <b>14,118.49</b> | <b>8,438.48</b>  |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars                                   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>            |   |          |                 |                 |
| 1                              | TO SPRAY UNDERCOATING IN REPAIR               | New      | 200.00          | 30.00           |
| 2                              | T DISM/REWIRE DAMAGED PORTION                 | New      | 180.00          | 30.00           |
| 3                              | TO DISM/REFIX REAR WINDSCREEN GLASS           | New      | 180.00          | 120.00          |
| 4                              | TO DISM /RENEW REAR REVERSE SENSOR /CAMERA    | New      | 200.00          | 100.00          |
| 5                              | TO RENEW REAR BUMPER LOWER SPOILER            | New      | 200.00          | 0.00            |
| 6                              | TO DISM/RENEW REAR EXHAUST PIPE               | New      | 150.00          | 60.00           |
| 7                              | TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS | New      | 1,200.00        | 600.00          |
| 8                              | TO PUTTY AND RESPRAY DAMAGED PORTION          | New      | 1,000.00        | 600.00          |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>3,310.00</b> | <b>1,540.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >