

ASS. REC. BY:

REF:

CS/CTI 22003663/Any3

create mermen ✓

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA 774YT. Yr Regn: 2016, March.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Tucson. C.C. 1999.

Colour: Blue. A/C: Insured / Std / NI / NA

Sp. Reading: 91525. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHJ3813MGU184975

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18.

R: 225/55R18.

BS / DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 20/04/22

Survey held at Unimol.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP China.</u>
	<u>Adrian confirmed Lump sum \$7900 and 5 days</u>
	<u>(Red. \$9528.49, 55%)</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?

1) 8/12/22

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:



Site Insp (\$



Interview (\$



Test Drive (\$

Report Form 1

TP - CTI

Lump Sum / R.E.D. /

7900



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

KMHJ3813MG4184975

TP China
Hui Rong

LKK

DATE: 24/04/2022 OUR REF: UAPL1523
REPAIR ESTIMATE TO THE HYUNDAI TUCSON NO. SLA7744T

- 1 REAR TAILGATE ASSY *Defect*
- 1 RE/R TAILGATE LAMP. (R) *Crushed*
- 1 REAR TAILGATE INNER LOCK *Defect*
- 1 REAR TAILGATE STRIKER *New*
- 2 REAR TAILGATE HINGES *New*
- 1 REAR TAILGATE WEATHERSTRIP *ut*
- 1 REAR TAILGATE HYUNDAI EMBLEM ASSY *New*
- 1 REAR TAILGATE TUCSON EMBLEM
- 2 REAR TAILGATE NUMBER PLATE LAMP *Not New*
- 1 REAR TAILGATE OUTER GARNISH *Defect*
- 1 REAR TAILGATE OUTER GARNISH BRACKET *Crushed*
- 1 REAR TAILGATE INNER TRIM BOARD *Crushed*
- 1 REAR TAILGATE STAY ABSORBER *New*
- 1 REAR TAILGATE INNER HANDLE GARNISH *New*
- 1 REAR TAILGATE GLASS ASSY *Shattered*
- 1 REAR TAILGATE WIPER MOTOR ASSY *New*
- 1 REAR TAILGATE WIPER ARM *New*
- 1 REAR TAILGATE WIPER BLADE *New*
- 1 REAR TAILGATE GLASS MOULDING
- 1 REAR TAILLAMP ASSY (R) *Crushed*
- 1 REAR BUMPER FACE (TOP) *Defect*
- 1 REAR BUMPER FACE (LOWER)
- 1 REAR BUMPER REINFORCEMENT *Crushed*
- 1 REAR BUMPER INNER SPONGE *New*
- 2 REAR BUMPER SIDE RETAINER *New*
- 1 REAR BUMPER TOW COVER GARNISH *Defect*
- 1 REAR R/H BUMPER REFLECTOR LAMP *Crushed*
- 8 REAR BUMPER CLIPS *New*
- 1 REAR EXHAUST BOX *New*
- 1 TAIL END PANEL *New*
- 1 PANEL LINING *Defect*

\$	1,938.00	1758
\$	686.20	
\$	667.00	395
\$	38.70	X
\$	196.80	X
\$	159.80	✓
\$	48.30	✓
\$	88.40	✓
\$	90.40	X
\$	618.40	✓
\$	145.70	✓
\$	338.80	✓
\$	599.20	X
\$	42.60	X
\$	1,644.80	1358
\$	889.60	585
\$	222.40	X
\$	84.60	X
\$	105.60	✓
\$	886.60	✓
\$	755.80	✓
\$	543.20	✓
\$	432.80	271
\$	286.50	X
\$	68.00	X
\$	25.80	✓
\$	102.70	✓
\$	48.00	30
\$	914.80	X
\$	785.80	X
\$	120.80	✓
\$	13,576.10	
\$	1,357.61	
\$	12,218.49	

LESS 10%.....

20%:

9623.10

7218.48



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三
AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/000

SPECIAL NETT:-

- 1 REAR NUMBER PLATE *Not rec*
- 1 SET REAR CCTV CAMERA *Not rec*
- 1 REAR TAILGATE OUTER GARNISH CHROME STRIP *Not rec*
- 1 REAR BUMPER TOP CHROME STRIP GARNISH *Not rec*
- 1 REAR BUMPER LOWER SPOILER *Not rec*
- 1 REAR BUMPER REVERSE SENSOR *Not rec*
- 1 REAR WINDSCREEN RUBBER SEALANT *Not rec*
- 1 REAR EXHAUST CHROME PIPE *Not rec*

\$ 50.00 X
\$ 420.00 X
\$ 180.00 150
\$ 220.00 180
\$ 550.00 ✓
\$ 280.00 200
\$ 80.00 60
\$ 120.00 80

1220

LABOUR CHARGES:-

TO SPRAY UNDERCOATING IN REPAIR

TO DISM/REWIRE DAMAGED PORTION

TO DISM/REFIX REAR WINDSCREEN GLASS

TO DISM/RENEW REAR REVERSE SENSOR/CAMERA

TO RENEW REAR BUMPER LOWER SPOILER

TO DISM/RENEW REAR EXHAUST PIPE

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS

TO PUTTY AND RESPRAY DAMAGED PORTION

\$ 200.00 30
\$ 180.00 30
\$ 180.00 120
\$ 200.00 100
\$ 200.00 X
\$ 150.00 60
\$ 1,200.00 600
\$ 1,000.00 600
\$ 17,428.49

1540

total 9978.48

L/S: 7-9K

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



POLICE FORCE
SINGAPORE

