

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003664/APA3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070134476
Claimant Vehicle No :	SMK5398H	Insured Vehicle No :	SKK3344A
Date of Loss:	14/04/2022	Nature of Claim:	TP
		Claim No:	6692525353SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK5398H		
Make & Model:	TOYOTA VIOS, 1.5 G (A)	Engine No:	2NRX434021
Reg. Date:	15/04/2019 (Man. Year: 2019)	Chassis No:	MR2B23F3101171851
Colour:	Bronze	Odometer:	43966 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,071.67	9,854.55	3,217.12	24.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,370.00	4,090.00	2,280.00	35.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,441.67	13,944.55	5,497.12	28.27
+ GST 7.00/7.00% (S\$)	1,360.92	976.12	384.80	28.27
Nett Amount (S\$)	20,802.59	14,920.67	5,881.92	28.27
+ Car Rental (12.0 x S\$100.00/day + 7.00% GST) (S\$)		1,284.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,206.67		

INSPECTION

Date of Assignment:	19/04/2022	Kang Car Repairers Pte Ltd (HQ)
Date Inspected:	19/04/2022 Inspected At:	No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
Estimated Period of Repair:	11.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	758.70 FL	*758.70 FL
2	2		*BOOT LID HINGE	Bent	155.60 FL	*155.60 FL
3	1		*BOOT LID LOGO	Necessary	52.20 FL	*52.20 FL
4	1		*BOOTLID G EMBLEM	Necessary	42.20 FL	*42.20 FL
5	1		*BOOT LID LOCK	Damaged	360.40 FL	*360.40 FL
6	1		*BOOT LID LOCK CHECKER	Not Necessary	49.20 FL	*- FL
7	1		*BOOT LID RUBBER	Cut	166.40 FL	*166.40 FL
8	1		*BOOT LID LAMP LH	Not Necessary	230.30 FL	*- FL
9	1		*BOOT LID LAMP RH	Not Necessary	230.30 FL	*- FL
10	1		*BOOT LID TRIM	Not Necessary	187.70 FL	*- FL
11	1		*REAR FENDER RH	Repair	804.80 FL	*- FL
12	1		*REAR FENDER TRIM RH	Deformed	355.90 FL	*355.90 FL
13	1		*TAIL LAMP -RH	Cracked	397.50 FL	*397.50 FL
14	1		*TAIL LAMP -LH	Not Necessary	397.50 FL	*- FL
15	1		*REAR LH FENDER TRIM	Not Necessary	355.90 FL	*- FL
16	1		*REAR PANEL	Dented	680.00 FL	*680.00 FL
17	1		*REAR PANEL TRIM	Deformed	232.20 FL	*232.20 FL
18	1		*REAR PANEL ANTENNA	Cracked	167.20 FL	*167.20 FL
19	1		*SPARE TYRE PANEL RH SPONGE	Deformed	128.80 FL	*128.80 FL
20	1		*SPARE TYRE PANEL LH SPONGE	Not Necessary	128.80 FL	*- FL
21	1		*REAR BUMPER	Distorted	452.20 FL	*452.20 FL
22	1		*REAR BUMPER REINFORCEMENT	Dented	316.60 FL	*316.60 FL
23	2		*REAR BUMPER SIDE RETAINER	Necessary	263.80 FL	*263.80 FL
24	2		*REAR BUMPER SMALL RETAINER	Not Necessary	102.20 FL	*- FL
25	1		*REAR BUMPER REFLECTOR RH	Cracked	162.80 FL	*162.80 FL
26	1		*BONNET	Dented	853.70 FL	*853.70 FL
27	2		*BONNET HINGE	Bent	175.80 FL	*175.80 FL
28	1		*BONNET LOCK	Damaged	195.10 FL	*195.10 FL
29	1		*FRT BRACE PANEL	Bent	128.80 FL	*128.80 FL
30	1		*FRT GRILLE	Cracked	268.80 FL	*65.00 FL
31	1		*FRT GRILLE EMBLEM	Necessary	72.20 FL	*72.20 FL
32	1		*FRT GRILLE EMBLEM BASE	Cracked	213.30 FL	*213.30 FL
33	2		*FRT GRILLE CHROME	Cracked	122.80 FL	*122.80 FL
34	1		*FRONT TOP GRILLE GARNISH COVER	Deformed	148.40 FL	*148.40 FL
35	1		*FRT GRILLE RUBBER	Not Necessary	61.20 FL	*- FL
36	1		*HEADLAMP LH	Cracked	1,254.60 FL	*1,254.60 FL
37	1		*HEADLAMP RH	Cracked	1,254.60 FL	*1,254.60 FL
38	1		*FRT BUMPER	Deformed	495.70 FL	*495.70 FL
39	1		*FRT BUMPER REINFORCEMENT	Bent	372.10 FL	*372.10 FL
40	1		*FRT BUMPER CENTRE GRILLE	Deformed	212.70 FL	*212.70 FL
41	1		*FRT BUMPER BOTTOM GRILLE	Deformed	388.20 FL	*388.20 FL
42	1		*FRT TOWING COVER	Not Necessary	48.50 FL	*- FL
43	1		*FRT BUMPER RH DAYLIGHT	Cut	279.80 FL	*279.80 FL
44	1		*FRT BUMPER LH DAYLIGHT	Cut	279.80 FL	*279.80 FL
45	1		*RADIATOR UNDER COVER	Not Necessary	209.30 FL	*- FL
46	1		*AIR CONDENSER	Deformed	935.90 FL	*935.90 FL
47	3		*AIRCON CONDENSER RH SIDE GARNISH	Cracked	154.80 FL	*154.80 FL
48	1		*REAR NUMBER PLATE	Deformed	50.00 FS	*50.00 FS
49	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
50	1		*SET BOOT LID TRIM CLIPS	Not Necessary	60.00 FS	*- FS
51	1		*SET REAR FENDER TRIM CLIPS RH	Necessary	60.00 FS	*30.00 FS
52	1		*SET REAR FENDER TRIM CLIPS LH	Not Necessary	60.00 FS	*- FS
53	1		*REAR WINDSCREEN SEAL	Not Necessary	60.00 FS	*- FS
54	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
55	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

4/28/23, 4:33 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET REVERSE SENSORS	Damaged	400.00 FS	*360.00 FS
57	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
58	1		*SET FRT GRILLE CLIPS	Necessary	60.00 FS	*20.00 FS
59	1		*SET FRT BUMPER SMALL GRILLE CLIPS	Necessary	40.00 FS	*10.00 FS
60	1		*SET FRT BUMPER GRILLE CLIPS	Necessary	40.00 FS	*30.00 FS
61	1		*FRT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
62	1		*SET RADIATOR UNDER COVER CLIP	Not Necessary	60.00 FS	*- FS
63	1		*BOOT LID VIOS EMBLEM	Necessary	43.60 FL	*43.60 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					16,908.90	12,939.40
- List Item Discount on L Items 25.00/25.00% (S\$)					3,837.23	3,084.85
Total Parts (S\$)					13,071.67	9,854.55
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	0.00
3	TO REMOVE AND REFIT SEAT CUSHION & TRIM	New	250.00	60.00
4	TO REMOVE AND REFIT REVERSE CAMERA	New	80.00	50.00
5	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
6	TO SPRAY PAINT SEALANT	New	120.00	60.00
7	(REAR) TO SPRAY PAINTING	New	1,500.00	1,100.00
8	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS	New	1,500.00	1,100.00
9	TO CHECK WIRING	New	50.00	30.00
10	TO REFILL AIRCON GAS	New	120.00	60.00
11	TO SPRAY PANEL SEALANT	New	100.00	0.00
12	(FRONT) TO SPRAY PAINTING	New	1,200.00	750.00
13	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING /WELDING WORKS	New	1,200.00	800.00
Gross Labour Cost (S\$)			6,370.00	4,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >