

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22003666/Rty3e2	
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	11/05/2022	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBG 8308A	Veh. Inspected		GBH 4132K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC05/025696	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		20/04/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE VAN TURBO 5DR	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JTFHT02P600242416	Colour		GREY	
	Odometer	109457 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195R15C	MICHELIN		6 mm	
	L/H Front Tyre	195R15C	MICHELIN		6 mm	
	R/H Rear Tyre	195R15C	MICHELIN		6 mm	
	L/H Rear Tyre	195R15C	MICHELIN		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR N/S BODY.				
5.	•	General Information				
	Accident Date	18/04/2022	Inspect Date / 1	Гіте	26/04/2022 (03:19 PM)	
	Survey held at	HIAP LEK AUTOMOBILE TRADING				
		160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22003666/Rty3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser